



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|--------------|------------|--|---|----------------|-------------|
| PAD | 26-044 | 2026-04-01 | Equipment / Furnishings - Emergency Locator Transmitter - Modification / Inspection | ISSOIRE AVIATION APM 30 | | 25 |
| AD | 2026-0072 | 2026-04-01 | Power Plant - Engine Mount Fitting - Inspections / Replacement | LEONARDO S.p.A. HELICOPTERS AW189 | 2026-04-15 | 71 |
| AD | 2026-0073 | 2026-04-01 | Fuel - Standby Fuel Pump - Operational Check | AIRBUS S.A.S. A330 | 2026-04-15 | 28 |
| PAD | 26-043 | 2026-04-01 | Electrical Systems Installation - Battery Retaining Rods - Identification / Replacement | AIRBUS S.A.S. A318 A319 A320 A321 | | 92 |
| SIB | SAIB-2026-08 | 2026-03-31 | Main Landing Gear - Wipaire Model 3000A and 3450A Wipline amphibian floats | MAULE AEROSPACE TECHNOLOGY M-6 M-7 Safety Information Bulletin Airworthiness TEXTRON AVIATION INC. 180 182 (Skylane) 185 (Skywagon) 206/U206 (Super Skywagon) WIPAIRE INC. EASA STC 10047945 FAA STC SA01156CH FAA STC SA01185CH FAA STC SA01272CH FAA STC SA01320CH FAA STC SA01412CH | | |
| AD | CF-2026-15 | 2026-03-31 | Navigation - Head-Up Display Application Software Issue in Avionic Software Version 5.8 - Amendment | BOMBARDIER BD-700 | 2026-04-08 | 34 |
| AD | 2026-0071 | 2026-03-31 | Powerplant - Engine Shock Mounts - Replacement | TECNAM, Costruzioni Aeronautiche P2006T | 2026-04-14 | 71 |
| PAD | 26-042-CN | 2026-03-30 | CANCELLED: Engine - Intermediate Pressure Turbine Blades - Inspection | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG TRENT 1000 | | 72 |
| PAD | 26-041-CN | 2026-03-30 | CANCELLED: Engine - Intermediate Pressure Turbine Blade Rear Seal Fins - Inspection | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG TRENT 1000 | | 72 |
| EAD | 2026-0070-E | 2026-03-30 | Flight Controls - Airbrakes Bellcrank - Inspection | PIPISTREL VERTICAL SOLUTIONS d.o.o. Virus SW | 2026-04-01 | 27 |
| PAD | 26-040 | 2026-03-30 | Flights Controls - Trimmable Horizontal Stabilizer Actuator Ballscrew Lower Splines - Inspection / Replacement | AIRBUS S.A.S. A318 A319 A320 A321 | | 27 |
| SIB | 2026-02 | 2026-03-30 | SZD-9 bis 1E - Notification of unapproved parts installed | JEZOW, ZAKLAD SZYBOWCOWY (Bocian) Safety Information Bulletin Airworthiness | | |
| ADR | 2026-0069-E | 2026-03-27 | Fuel - Fuel Tank - Inspection | AIRBUS MILITARY SL A400M | | 28 |
| AD | 2026-0067 | 2026-03-27 | Engine Exhaust - Exhaust Pipes - Modification / Inspection | ACC COLUMBIA Jet Service GmbH EASA STC 10048730 DIAMOND AIRCRAFT INDUSTRIES DA 42 | 2026-04-10 | 78 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|-----------------|------------|--|---|----------------|-------------|
| AD | 2026-0068 | 2026-03-27 | Operational Limitation Placards and Markings - Placards - Installation | AVIONIC SPOLKA JAWNA SZD-56-2 | 2026-04-03 | 11 |
| AD | 2026-0066 | 2026-03-27 | Equipment and Furnishings - Life Raft / Safety Pin - Operational Restriction / Inspection | LEONARDO S.p.A. HELICOPTERS AW189 | 2026-04-02 | 25 |
| AD | BR-2020-01-02R4 | 2026-03-27 | [Correction] Nacelles / Pylons - Engine Inboard and Outboard Pylon Lower Link Lugs - Inspection / Repair | EMBRAER S.A. ERJ 170 ERJ 190 | 2026-03-31 | 54 |
| PAD | 26-039 | 2026-03-26 | Flight Controls - Stabilizers / Elevator lower panels - Inspection / Rework | ATR ATR42 | | 27 |
| AD | G-2026-0001 | 2026-03-26 | Equipment / Furnishings - Passenger Seats - Modification | APPLIANCES ATA 25 EQUIPMENT / FURNISHINGS | 2026-03-26 | 25 |
| AD | 2026-0064 | 2026-03-26 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 4, System Equipment Maintenance Requirements - Amendment | AIRBUS S.A.S. A318 A319 A320 A321 | 2026-04-09 | 05 |
| AD | 2026-0063 | 2026-03-26 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 1, Safe Life Airworthiness Limitation Items - Amendment | AIRBUS S.A.S. A318 A319 A320 A321 | 2026-04-09 | 05 |
| AD | 2026-0020R1 | 2026-03-26 | Main Rotor - Main Rotor Pitch Rod End - Inspection | AIRBUS HELICOPTERS H160 | 2026-04-02 | 62 |
| EAD | 2026-0065-E | 2026-03-25 | Landing Gear - Emergency Autoland Braking System / Brake Pipe Assembly - Replacement | PILATUS AIRCRAFT LTD PC-12 | 2026-03-27 | 32 |
| AD | 2026-0062 | 2026-03-25 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 5, Fuel Airworthiness Limitations - Amendment | AIRBUS S.A.S. A318 A319 A320 A321 | 2026-04-08 | 05 |
| AD | 2026-0061 | 2026-03-25 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 3, Certification Maintenance Requirements - Amendment | AIRBUS S.A.S. A318 A319 A320 A321 | 2026-04-08 | 05 |
| PAD | 26-038 | 2026-03-24 | Rotorcraft Flight Manual - Section Emergency Procedures - Amendment Integrated Modular Avionics - Ethernet Network - Inspection / Modification | AIRBUS HELICOPTERS DEUTSCHLAND MBB-BK 117 | | 42 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|-----------------|------------|--|---|----------------|-------------|
| AD | BR-2025-08-01R1 | 2026-03-24 | H8 ALS Industria Aeronautica LTDA: NOT ELIGIBLE FOR ADOPTION - EASA DECISION ATTACHED See: EASA Suspected Unapproved Parts Details-> Parts manufactured by H8 ALS Industria Aeronautica LTDA | EMBRAER EMB-121 (Xingu)PIPER AIRCRAFT INC. PA-23 (Apache) PA-23 (Aztec) PA-24 (Comanche) PA-28 (Archer) PA-28 (Cadet) PA-28 (Cherokee) PA-28 (Dakota) PA-28 (Warrior) PA-28R (Arrow) PA-30 (Twin Comanche) PA-31 (Navajo) PA-32 (Cherokee Six) PA-32 (Piper 6X) PA-32 (Saratoga) PA-32R (Lance) PA-34 (Seneca) PA-44 (Seminole)TEXTRON AVIATION INC. 150 172 (Skyhawk) 175 177 (Cardinal) 180 182 (Skylane) 185 (Skywagon) 188 (AGwagon) 206/U206 (Super Skywagon) 207 (Skywagon) 210 (Centurion) 336 337 (Super Skymaster) 401 402 411 | 2025-08-11 | 32 |
| AD | 2025-0166R1 | 2026-03-24 | Fuselage - Inner Cap and Frame Flange at Frame 68 Stringer 22 - Inspections | AIRBUS S.A.S. A318 A319 A320 A321 | 2026-03-31 | 53 |
| AD | 2025-0083R1 | 2026-03-24 | Equipment/Furnishings - Cargo Bulkhead Frame 24A Vertical Members - Inspection | AIRBUS S.A.S. A318 A319 A320 A321 | 2026-03-31 | 25 |
| PAD | 26-037 | 2026-03-23 | Fuselage - Cabin and Cargo Compartments Structural Parts - Inspection / Replacement | AIRBUS S.A.S. A330 | | 53 |
| PAD | 26-036 | 2026-03-23 | Fuselage - Structure Frames and Joints - Modification / Reinforcement | AIRBUS S.A.S. A340 | | 53 |
| AD | US-2026-05-15 | 2026-03-23 | Sidewall Light - Inspection | BOEING 777 | 2026-04-20 | 33 |
| SIB | SAIB-2026-01 | 2026-03-23 | Pitot/Static Anti-Ice System | BOEING 737Safety Information Bulletin Airworthiness | | |
| SIB | SAIB-2026-07 | 2026-03-23 | Main Landing Gear Attach Section - Trunnion Pins | LEARJET, INC. 23 24 25 28 29 31/35/36 55 60Safety Information Bulletin Airworthiness | | |
| AD | CF-2026-14 | 2026-03-20 | Engine - Engine Mount - Inspections | MHI RJ Aviation ULC CL-600 (Regional Jet) | 2026-04-01 | 71 |
| PAD | 26-035 | 2026-03-20 | ATA 71 - Powerplant - Air Intake Nose Cowl - Inspection | AIRBUS S.A.S. A330 | | 71 |
| AD | 2026-0060 | 2026-03-20 | Fuel - Fuel Low Pressure Shut-Off Valve - Leak Check | AIRBUS S.A.S. A330 A340 | 2026-04-03 | 28 |
| AD | 2026-0059 | 2026-03-19 | Time Limits / Maintenance Checks - Airworthiness Limitation Section Part 4, System Equipment Maintenance Requirements - Amendment | AIRBUS S.A.S. A330 | 2026-04-02 | 05 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|----------------|------------|---|--|----------------|-------------|
| AD | 2026-0057 | 2026-03-19 | Equipment / Furnishings - Personal Locator Beacons installed on Emergency Life-Rafts - Operational Check | AIRBUS HELICOPTERS EC175 | 2026-04-02 | 25 |
| AD | 2025-0104R1 | 2026-03-19 | Aircraft Flight Manual - Sections Limitations and Normal Procedures - Amendment Master Minimum Equipment List - Amendment Pneumatic - High Pressure Valve - Modification / Inspection / Replacement | AIRBUS S.A.S. A330 | 2026-04-02 | 36 |
| SIB | CASA-2026-02 | 2026-03-18 | Insufficient Clearance Between Engine Fuel-Feed Line and Collector Tank Upper Skin Stringer | BOMBARDIER BD-700Safety Information Bulletin Airworthiness | | |
| AD | 2026-0001-E-CN | 2026-03-18 | [Correction] CANCELLED: Main Rotor - Main Rotor Pitch Rod End Bearings - Replacement | AIRBUS HELICOPTERS H160 | 2026-03-10 | 62 |
| AD | 2026-0058 | 2026-03-17 | Stabilizers - NACA Vent Intake Panel - Modification | AIRBUS S.A.S. A330 | 2026-03-31 | 55 |
| ADR | 2025-0293R1 | 2026-03-17 | Fuselage - Inner Flange Glare Frames - Inspection | AIRBUS MILITARY SL A400M | | 53 |
| AD | US-2026-05-07 | 2026-03-16 | Wings - Forward Lower Fastener Holes of the Underwing Longeron Fitting - Inspection | BOEING 767 | 2026-04-16 | 57 |
| AD | US-2026-05-03 | 2026-03-16 | Fuselage - Stringers of the Skin Lap Joint - Inspections | BOEING 767 | 2026-04-16 | 53 |
| AD | US-2026-05-01 | 2026-03-16 | Navigation - Integrated Surveillance System Processor Unit Hardware - Replacement | BOEING 787 | 2026-04-16 | 34 |
| AD | 2026-0056 | 2026-03-16 | Powerplant - Engine Firewalls - Modification | AIRBUS HELICOPTERS SA/AS 365 / EC 155 | 2026-03-30 | 71 |
| AD | 2026-0054 | 2026-03-13 | Wings - Flap Lever Assembly - Modification | ISSOIRE AVIATION APM 20 APM 30 APM 40 (Simba) | 2026-03-27 | 57 |
| PAD | 26-034 | 2026-03-13 | Flight Controls - Aileron, Elevator and Rudder Servocontrols - Replacement | AIRBUS S.A.S. A350 | | 27 |
| AD | 2026-0053 | 2026-03-13 | Air Conditioning - Air Conditioning Pack - Inspection | DASSAULT AVIATION Falcon 7X | 2026-03-27 | 21 |
| AD | 2026-0055 | 2026-03-13 | Fuselage - Forward Fuselage Skin Panels - Inspection | AIRBUS S.A.S. A319 A320 A321 | 2026-03-20 | 53 |
| SIB | CASA-2026-03 | 2026-03-12 | Localizer Signal Deviation Disturbances | AIRBUS CANADA LP BD-500 (A220 Series)Safety Information Bulletin Airworthiness | | |
| AD | 2026-0052 | 2026-03-12 | Instruments - Fuse Cover Attachment of Circuit Breaker Panel - Modification | AIRBUS HELICOPTERS AS 350 / EC 130 | 2026-03-26 | 31 |
| AD | 2026-0051 | 2026-03-12 | Fuel - Quantity Indicating Placard - Modification | VULCANAIR S.p.A. P.68 | 2026-03-26 | 28 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|---------------|------------|---|--|----------------|-------------|
| AD | CF-2026-13 | 2026-03-11 | Nacelles/Pylons - Upper and Side Pylon Link Assemblies - Replacement | AIRBUS CANADA LP BD-500 (A220 Series) | 2026-03-24 | 54 |
| AD | CF-2026-11 | 2026-03-11 | Fuselage - Forward Engine Support Frame Fuselage Station - Inspection | MHI RJ Aviation ULC CL-600 (Regional Jet) | 2026-03-17 | 53 |
| AD | 2026-0050 | 2026-03-11 | Auto Flight - Automatic Flight Control System - Functional Check Flight | AIRBUS HELICOPTERS DEUTSCHLAND EC135/635 MBB-BK 117 | 2026-03-18 | 22 |
| AD | 2026-0049 | 2026-03-11 | Engine - Full Authority Digital Electronic Control Software - Replacement | CFM INTERNATIONAL LEAP-1A/-1C | 2026-03-25 | 72 |
| AD | US-2026-03-06 | 2026-03-10 | [Correction] Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | TEXTRON AVIATION INC. 525 (CitationJet) | 2026-03-13 | 55 |
| AD | US-2026-04-11 | 2026-03-10 | Reciprocating Engine - Connecting Rod Bushing - Inspections / Replacement | LYCOMING ENGINES AEIO-320 AEIO-360 AEIO-390 AEIO-540 AEIO-580 AIO-320 AIO-360 HIO-360 HIO-390 HIO-540 HO-360 IO-320 IO-360 IO-390 IO-540 IO-580 IO-720 IVO-360 IVO-540 LHIO-360 LIO-320 LIO-360 LO-360 LTIO-540 LTO-360 O-233 O-235 O-290 O-320 O-340 O-360 O-435 O-540 SO-580 TEO-540 TIGO-541 TIO-360 TIO-540 TIO-541 TIVO-540 TO-360 TVO-435 TVO-540 VO-360 VO-435 VO-540 VSO-580 | 2026-04-08 | 85 |
| AD | 2026-0048 | 2026-03-10 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Airworthiness Limitations Items and Safe life Items - Amendment | FOKKER SERVICES F28 | 2026-03-24 | 05 |
| AD | 2026-0047 | 2026-03-10 | Fuselage - Door Frames Holes - Inspection | AIRBUS S.A.S. A300-600 A310 | 2026-03-24 | 53 |
| AD | US-2026-04-10 | 2026-03-09 | Satellite Communications - High Gain Antenna Adapter Plate - Inspection | BOEING 767 | 2026-04-10 | 23 |
| AD | 2026-0046 | 2026-03-09 | [Correction] Landing Gear - Landing Gear Selector Valve - Functional Check | ATR ATR42 ATR72 | 2026-03-20 | 32 |
| AD | 2023-0176R1 | 2026-03-09 | [Correction] Fuselage - Cargo Compartment Panels Sealing Tape - Inspection | AIRBUS S.A.S. A350 | 2026-03-13 | 53 |
| AD | CF-2026-10 | 2026-03-06 | Air Conditioning - Outflow Valve Manual Mode Direct Current Motor Failure | AIRBUS CANADA LP BD-500 (A220 Series) | 2026-03-13 | 21 |
| AD | US-2026-04-09 | 2026-03-05 | Turbine Engine - High-Pressure Compressor Stage 5 Blisks - Replacement | GENERAL ELECTRIC GENx | 2026-03-11 | |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|---------------|------------|--|--|----------------|-------------|
| EAD | CF-2026-12 | 2026-03-04 | Levelling and Weighing - Aft Moveable Ballast Box Assembly Door Hinge Failure | BELL TEXTRON CANADA LTD (BTCL) 505 (Jet Ranger X) | 2026-03-04 | 08 |
| AD | 2026-0043 | 2026-03-04 | Electrical System Installation - Inspections | AIRBUS DEFENCE & SPACE S.A. C-295 | 2026-03-18 | 92 |
| AD | 2026-0044 | 2026-03-04 | SAFRAN ELECTRONICS & DEFENSE BEACONS: Emergency Locator Transmitter - Modification | APPLIANCES ATA 25 EQUIPMENT / FURNISHINGS | 2026-02-25 | 25 |
| AD | 2026-0045 | 2026-03-04 | Rotors Flight Control - Collective Stick Torque Tube Assembly - Inspection / Replacement | LEONARDO S.p.A. HELICOPTERS A109/A119 | 2026-03-18 | 67 |
| AD | 2026-0042 | 2026-03-03 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 1 - Safe Life Airworthiness Limitation Items - Amendment | AIRBUS S.A.S. A330 | 2026-03-17 | 05 |
| AD | BR-2026-01-02 | 2026-03-02 | [Correction] Horizontal Stabilizers Elevator and Wing Aileron Control Systems - Inspections | EMBRAER EMB-545/-550 (Legacy 500) | 2026-01-21 | |
| AD | 2026-0041 | 2026-02-27 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | DASSAULT AVIATION Falcon 2000 | 2026-03-13 | 05 |
| AD | 2026-0040 | 2026-02-27 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | DASSAULT AVIATION Falcon 2000 | 2026-03-13 | 05 |
| AD | US-2026-04-06 | 2026-02-27 | Wings - Scimitar Blended Winglets - Inspection | BOEING 757 | 2026-02-26 | 57 |
| AD | 2026-0039 | 2026-02-27 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | AIRBUS HELICOPTERS EC175 | 2026-03-13 | 05 |
| SIB | SAIB-2026-04 | 2026-02-26 | Propeller Hub Section | HAMILTON SUNDSTRAND 54HSafety Information Bulletin Airworthiness | | |
| SIB | CASA-2026-01 | 2026-02-26 | Spoiler Spigot Shim Missing at Multifunction Spoiler Actuator Installation | BOMBARDIER BD-700Safety Information Bulletin Airworthiness | | |
| AD | 2026-0038 | 2026-02-26 | Air Conditioning - Integrated Air System Control - Modification | ATR ATR42 ATR72 | 2026-03-12 | 21 |
| AD | 2026-0030 | 2026-02-26 | Wings - Movable Flap Track Fairings 2 and 5 / Forward Attachments - Inspection | AIRBUS S.A.S. A380 | 2026-03-12 | ATA 57 |
| PAD | 25-098R1 | 2026-02-26 | SAFRAN SEATS: Third Occupant Seat Bottom Equipped Screw - Replacement | APPLIANCES ATA 25 EQUIPMENT / FURNISHINGS | | 25 |
| AD | US-2026-04-05 | 2026-02-25 | Electrical Power - AFM Operating Procedures - Amendment | BOEING 737 | 2026-02-24 | 24 |
| AD | 2026-0036 | 2026-02-25 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitation Items - Amendment | AIRBUS S.A.S. A330 | 2026-03-11 | 05 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|-------------|------------|--|--|----------------|-------------|
| AD | 2026-0035 | 2026-02-25 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 1 - Safe Life Airworthiness Limitation Items - Amendment | AIRBUS S.A.S. A330 | 2026-03-11 | 05 |
| AD | 2026-0037 | 2026-02-25 | Equipment/Furnishings - Evacuation Slide/Inflation Hose Assemblies - Replacement | AIRBUS S.A.S. A318 A319 A320 A321 | 2026-03-11 | 25 |
| PAD | 26-032 | 2026-02-23 | Hydraulic Power - Engine-driven Pump - Software Update / Modification Aircraft Flight Manual - Abnormal and Emergency Procedures - Amendment | AIRBUS S.A.S. A350 | | 29 |
| AD | 2026-0034 | 2026-02-23 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2, Damage Tolerant Airworthiness Limitation Items - Amendment | AIRBUS S.A.S. A350 | 2026-03-09 | 05 |
| AD | 2026-0033 | 2026-02-20 | Engine - High-Pressure Turbine Inner Stationary Seal - Inspection | CFM INTERNATIONAL CFM56-5B CFM56-5C CFM56-7B | 2026-03-06 | 72 |
| AD | 2026-0032 | 2026-02-19 | Tail Rotor - Tail Rotor Blades - Inspection | AIRBUS HELICOPTERS DEUTSCHLAND EC135/635 | 2026-03-05 | 64 |
| AD | 2026-0031 | 2026-02-19 | Tail Rotor - Tail Rotor Blades - Inspection | AIRBUS HELICOPTERS DEUTSCHLAND EC135/635 | 2026-03-05 | 64 |
| AD | CF-2026-08 | 2026-02-12 | Equipment/Furnishings - Overhead Stowage Compartment - Handle Rod Disconnected | AIRBUS CANADA LP BD-500 (A220 Series) | 2026-02-19 | 25 |
| AD | CF-2026-09 | 2026-02-12 | Ice and Rain Protection - Engine Cowl Anti-Ice - Ejector Pipe Chafing | MHI RJ Aviation ULC CL-600 (Regional Jet) | 2026-02-19 | 30 |
| AD | 2026-0029 | 2026-02-12 | Tail Rotor Drive - Tail Gear Box Input Flange - Functional Checks | AIRBUS HELICOPTERS SA/AS 365 / EC 155 | 2026-02-26 | 65 |
| AD | 2026-0028 | 2026-02-11 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitation Items - Amendment | AIRBUS S.A.S. A318 A319 A320 A321 | 2026-02-25 | 05 |
| AD | 2026-0027 | 2026-02-11 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | SAFRAN HELICOPTER ENGINES ARRIUS 2 | 2026-02-25 | 05 |
| AD | 2024-0215R1 | 2026-02-11 | Main Rotor - Hub Sleeves - Inspection | AIRBUS HELICOPTERS SA 330 / AS 332 / EC 225 | 2026-02-18 | 62 |
| AD | 2025-0297R1 | 2026-02-10 | AEROSPACE & DEFENSE OXYGEN SYSTEMS SaS (Part of SAFRAN AEROSYSTEMS): Portable Breathing Equipment - Removal From Service | APPLIANCES ATA 35 OXYGEN | 2026-02-17 | 35 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|---------------|------------|--|---|----------------|-------------|
| AD | 2026-0026 | 2026-02-10 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitation Items - Amendment | AIRBUS S.A.S. A340 | 2026-02-24 | 05 |
| AD | 2026-0025 | 2026-02-10 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitation Items - Amendment | AIRBUS S.A.S. A330 | 2026-02-24 | 05 |
| SIB | 2026-01 | 2026-02-09 | Landing Gear - Degraded Anti-Skid Performance on Contaminated Runways | AIRBUS CANADA LP BD-500 (A220 Series) Safety Information Bulletin Airworthiness | | |
| AD | 2025-0294R1 | 2026-02-09 | B/E AEROSPACE FISCHER GmbH: Medical Seats - Modification | APPLIANCES ATA 25 EQUIPMENT / FURNISHINGS | 2026-02-16 | 25 |
| AD | US-2026-02-10 | 2026-02-06 | Water / Waste - Faucet Control Module - Inspections / Replacement | BOEING 787 | 2026-03-09 | 38 |
| AD | 2025-0228R1 | 2026-02-06 | Standard Practices and Structures - DECOMATIC Titanium Bolts - Replacement | DASSAULT AVIATION Falcon 2000 Falcon 7X Falcon 900EX | 2026-02-13 | 51 |
| AD | CF-2026-06 | 2026-02-05 | Landing Gear - Main Landing Gear Aft Door Mechanism - Lock Link Apex Pin/Bolt Fracture | DE HAVILLAND AIRCRAFT OF CANADA LTD. DHC-8 | 2026-02-17 | 32 |
| AD | CF-2026-07 | 2026-02-05 | Ice and Rain Protection - Engine Cowl Anti-Ice - Ejector Pipe Chafing | MHI RJ Aviation ULC CL-600 (Regional Jet) | 2026-02-18 | 30 |
| AD | 2026-0024 | 2026-02-05 | Rotors Flight Control - Ball Bearing Control System - Inspections | AIRBUS HELICOPTERS DEUTSCHLAND EC135/635 | 2026-02-19 | 67 |
| AD | CF-2025-60R1 | 2026-02-04 | Fuselage - Tail Rotor Gearbox Support Assembly to Tailboom Attachment Discrepant Rivets | BELL TEXTRON CANADA LTD (BTCL) 429 | 2026-02-11 | 53 |
| AD | 2025-0283 | 2026-02-04 | [Correction] Nacelles / Pylons - Air Intake Cowl - Inspection | AIRBUS S.A.S. A350 | 2025-12-29 | 54 |
| AD | CF-2026-05 | 2026-02-03 | HONEYWELL ASCa Inc.: Emergency Locator Transmitter - Degraded Performance in High Temperature environment. | APPLIANCES ATA 25 EQUIPMENT / FURNISHINGS | 2026-02-13 | 25 |
| AD | 2026-0023 | 2026-02-02 | Engine Exhaust - Noise Suppressor / Muffler - Inspections | TECNAM, Costruzioni Aeronautiche P2010 | 2026-02-16 | 78 |
| AD | CF-2026-04 | 2026-02-02 | Landing Gear - Main Landing Gear Premature Tire Failure | DE HAVILLAND AIRCRAFT OF CANADA LTD. DHC-8 | 2026-02-11 | 32 |
| EAD | 2026-0022-E | 2026-01-29 | Fuselage - Intermediate Fuselage Frame 8 - Inspection | AIRBUS HELICOPTERS EC175 | 2026-02-02 | 53 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|---------------|------------|--|---|----------------|-------------|
| SIB | SAIB-2026-03 | 2026-01-29 | Emergency Equipment, Orion Safety Products Skyblazer II Red XLT Aerial Signal | Safety Information Bulletin Airworthiness | | |
| AD | 2026-0021 | 2026-01-29 | Fuselage - Mounts and Attachment - Checks / Replacement | AIRBUS HELICOPTERS AS 350 / EC 130 | 2026-02-05 | 53 |
| PAD | 26-015 | 2026-01-27 | Doors - Bulk Cargo Door Stop Screw - Ins | AIRBUS S.A.S. A350 | | 52 |
| ADR | 2026-0019 | 2026-01-26 | Fuselage - Ram Air Turbine Rod Assembly - Inspection | AIRBUS MILITARY SL A400M | | 53 |
| SIB | BEA-2026-01 | 2026-01-26 | Ice and Rain Protection - Replacement of Pitot #3 Heater Wiring | EMBRAER S.A. EMB-135 EMB-145 Safety Information Bulletin Airworthiness | | |
| AD | 2026-0018 | 2026-01-26 | Wings - Main Landing Gear Trunnion Block Fuse Pins and Retaining Pins - Inspection | AIRBUS S.A.S. A350 | 2026-02-09 | 57 |
| AD | 2026-0016 | 2026-01-26 | Flight Controls - Spoiler Electrical Control Unit - Replacement | DASSAULT AVIATION Falcon 7X | 2026-02-09 | 27 |
| AD | US-2026-01-03 | 2026-01-23 | Main Landing Gear - Airworthiness Limitations - Revision | GULFSTREAM AEROSPACE CORPORATION GVII | 2026-02-24 | 32 |
| AD | US-2026-01-02 | 2026-01-23 | Wings - Airworthiness Limitations - Revision | GULFSTREAM AEROSPACE CORPORATION GVI | 2026-02-24 | 57 |
| AD | 2026-0017 | 2026-01-23 | Equipment / Furnishings - Galley - Inspection | AIRBUS S.A.S. A318 A319 A320 A321 | 2026-02-06 | 25 |
| EAD | 2026-0015-E | 2026-01-22 | Stabilizers - Horizontal Stabilizer - Inspections | AIRBUS HELICOPTERS SA 330 / AS 332 / EC 225 | 2026-01-26 | 55 |
| SIB | SAIB-2026-02 | 2026-01-22 | Elevator Tab Control System | Safety Information Bulletin Airworthiness TEXTRON AVIATION INC. 1900 (Airliner) | | |
| SIB | CASA-2025-13 | 2026-01-22 | A220 PW1500G Oil System Inspection after Oil Debris Monitoring (ODM) Indication | AIRBUS CANADA LP BD-500 (A220 Series) Safety Information Bulletin Airworthiness | | |
| AD | CF-2026-03 | 2026-01-22 | Equipment/Furnishings - Emergency Locator Transmitter (ELT) G-Switch Jumper Wire missing | DIAMOND AIRCRAFT INDUSTRIES, INC. DA20 | 2026-02-04 | 25 |
| PAD | 26-009 | 2026-01-22 | Landing Gear - Main Landing Gear Bogie Pivot Pin and Bushes - Inspection | AIRBUS S.A.S. A350 | | 32 |
| AD | US-2026-01-06 | 2026-01-20 | Fuselage - Cargo Barrier Fitting Link - Inspection | BOEING 787 | 2026-02-20 | 53 |
| AD | US-2026-01-05 | 2026-01-20 | Wings - Aviation Partners Boeing (APB) Scimitar Blended Winglets Lower Stringer - Inspection / Maintenance Records Check | BOEING 757 | 2026-02-20 | 57 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|-----------------|------------|--|---|----------------|-------------|
| AD | US-2026-01-04 | 2026-01-20 | Fuselage - Ram Air Turbine Forward Fittings - Inspection | BOEING 787 | 2026-02-20 | 53 |
| AD | CF-2026-01 | 2026-01-20 | Tail Rotor - Incorrect Tailcone Assembly Part Number Identification Plate | BELL TEXTRON CANADA LTD (BTCL) (Jet Ranger X) 505 | 2026-01-26 | 64 |
| AD | 2026-0013 | 2026-01-20 | Rotorcraft Flight Manual - Limitations and Normal Procedures Section - Amendment | AIRBUS HELICOPTERS EC175 | 2026-02-03 | |
| AD | 2026-0014 | 2026-01-20 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 3 - Certification Maintenance Requirements - Amendment | AIRBUS S.A.S. A340 | 2026-02-03 | 05 |
| AD | 2024-0229R1 | 2026-01-20 | Main Rotor - Swashplate Bearing - Inspections | AIRBUS HELICOPTERS H160 | 2026-01-27 | 62 |
| AD | BR-2012-08-03R1 | 2026-01-20 | Cockpit Door Passive Lock Striker - Quick Release Pin and Hinges / Replacement | EMBRAER S.A. ERJ 190 | 2026-01-28 | |
| PAD | 26-008 | 2026-01-19 | Fuselage - Scuppers of the Engine Drain System - Modification | AIRBUS HELICOPTERS EC175 | | 53 |
| AD | 2026-0012 | 2026-01-19 | Landing Gear - Main Landing Gear Torque Link - Replacement | DASSAULT AVIATION Falcon 2000 Mystère-Falcon 50 | 2026-02-02 | 32 |
| AD | CF-2026-02 | 2026-01-16 | Fuselage Structure - Aft Pressure Bulkhead Stiffener Found Cracked | BOMBARDIER BD-700 | 2026-01-28 | 53 |
| AD | BR-2025-12-01 | 2026-01-15 | Aircraft Maintenance Manual - Airworthiness Limitations - Revision | EMBRAER EMB-545/-550 (Legacy 500) | 2025-12-22 | |
| AD | 2026-0011 | 2026-01-15 | Doors - Jettisonable Windows and Seals on the Sliding Doors and Fixed Panels - Modification | AIRBUS HELICOPTERS SA/AS 365 / EC 155 | 2026-01-29 | 52 |
| AD | 2026-0008 | 2026-01-15 | Ice and Rain Protection - Windows, Windshields and Doors / Left-Hand Windshield Heating Solid State Relay - Modification / Replacement | PILATUS AIRCRAFT LTD PC-24 | 2026-01-29 | 30 |
| AD | 2026-0010 | 2026-01-15 | Flight Controls - Control Column Pivoting Bearing - Inspection | DG AVIATION GmbH DG-800 | 2026-01-29 | 27 |
| AD | 2026-0009 | 2026-01-15 | Flight Controls - Control Column Pivoting Bearing - Inspection | DG AVIATION GmbH DG-100 DG-200 DG-300 DG-400 DG-600 | 2026-01-29 | 27 |
| AD | US-2026-01-01 | 2026-01-14 | Flight Controls - Aileron Fixed Balance Weights - Replacement | HONDA AIRCRAFT COMPANY LLC HA-420 | 2026-02-17 | 27 |
| AD | US-2025-26-04 | 2026-01-14 | Miscellaneous Hardware - Hydraulic Fuel Pressure Fuel Oil Cooler Fuel Tube Assembly (CP09 Tube Assembly) / Thermal Management System Clevis Mounts - Replacement | INTERNATIONAL AERO ENGINES LLC PW1100 / PW1400 | 2026-02-17 | 14 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|---------------|------------|--|---|----------------|-------------|
| AD | 2026-0007 | 2026-01-14 | Landing Gear - Component Life Limit - Implementation | AIRBUS S.A.S. A300 | 2026-01-28 | 32 |
| AD | 2025-0278R1 | 2026-01-14 | Equipment / Furnishings - Emergency Sea Anchor Pin - Inspection / Replacement | AIRBUS HELICOPTERS SA 330 / AS 332 / EC 225 | 2026-01-21 | 25 |
| AD | CF-2025-71 | 2026-01-13 | Time Limits/Maintenance Checks (TLMC) - New Airworthiness Limitations | PRATT & WHITNEY CANADA PW800 | 2026-01-13 | 05 |
| SIB | SAIB-2025-11 | 2026-01-13 | Rudder Control System | Safety Information Bulletin Airworthiness TEXTRON AVIATION INC. 150 152 F150 F152 | | |
| AD | 2026-0006 | 2026-01-13 | Doors - Canopy Jettison System - Inspection/Replacement | DIAMOND AIRCRAFT INDUSTRIES H 36 / HK 36 | 2026-01-27 | 52 |
| AD | 2026-0004 | 2026-01-13 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | LEONARDO S.p.A. HELICOPTERS AW189 | 2026-01-27 | 04 |
| AD | 2019-0262-CN | 2026-01-13 | CANCELLED: Flight Controls - Bonding Braid Screw and Pitch Tab Control Rod - Inspection / Repair | ATR ATR42 | 2026-01-13 | 27 |
| AD | 2016-0046-CN | 2026-01-13 | CANCELLED: Auto Flight - Auto Pilot and Yaw Damper - Operational Limitations / CANCELLED: Aircraft Flight Manual - Amendment | ATR ATR42 ATR72 | 2026-01-13 | 22 |
| AD | 2026-0005 | 2026-01-13 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | SAAB AB 340 | 2026-01-27 | 05 |
| AD | CF-2025-70 | 2026-01-12 | Flight Controls - Elevator and Rudder Power Control Units (PCUs) Rod End Fractures | MHI RJ Aviation ULC CL-600 (Regional Jet) | 2026-01-05 | 27 |
| AD | CF-2025-69 | 2026-01-12 | Fuel System - Potential Fuel Leak in Dry-Bay - Missing Sealant | DE HAVILLAND AIRCRAFT OF CANADA LTD. DHC-8 | 2026-01-05 | 28 |
| AD | 2026-0003 | 2026-01-12 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | LEONARDO S.p.A. HELICOPTERS AB139/AW139 | 2026-01-26 | 05 |
| AD | 2026-0002 | 2026-01-12 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | DASSAULT AVIATION Falcon 6X | 2026-01-26 | 05 |
| AD | US-2025-25-07 | 2026-01-09 | Turbine Engine - High-Pressure Turbine (HPT) Stage 1 and HPT Stage 2 Disks - Replacement | GENERAL ELECTRIC GE90 | 2026-02-06 | 72 |
| AD | BR-2026-01-01 | 2026-01-09 | Engines Operation in Ground Freezing Fog - Operational Limitations Revision | EMBRAER S.A. ERJ 190 | 2026-01-12 | |
| AD | CF-2025-67 | 2026-01-09 | Time Limits/Maintenance Checks (TLMC) - New and Revised Airworthiness Limitations (AWL) Tasks | AIRBUS CANADA LP BD-500 (A220 Series) | 2026-01-10 | 05 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|-------------------|------------|--|---|----------------|-------------|
| AD | ISR-I-35-26-01-01 | 2026-01-01 | Potential of arcing, fire and/or loss of crew oxygen supply due to insufficient clearances between electrical wiring and flexible oxygen hose | BOEING 747ISRAEL AEROSPACE INDUSTRIES LTD CAA Israel STC SA151 CAA Israel STC SA152 EASA STC 10014423 EASA STC 10015911 | 2026-01-01 | |
| SIB | 2025-11 | 2025-12-26 | [Correction] Chemical Oxygen Generator Instructions for Disposal | Safety Information Bulletin Airworthiness | | 35 |
| EAD | 2025-0298-E | 2025-12-23 | Main Rotor - Swashplate - Inspection | AIRBUS HELICOPTERS DEUTSCHLAND MBB-BK 117 | 2025-12-25 | 62 |
| AD | 2025-0296 | 2025-12-23 | Tail Rotor Drive - Tail Drive Line Rear Shaft and Damper - Inspections | AIRBUS HELICOPTERS H160 | 2026-01-06 | 65 |
| AD | 2025-0295 | 2025-12-22 | AIRCRAFT CABIN MODIFICATION - Equipment / Furnishings - Pallet Net - Limitation | APPLIANCES ATA 25 EQUIPMENT / FURNISHINGS | 2026-01-05 | 25 |
| AD | CF-2025-68 | 2025-12-19 | Landing Gear - Degraded Anti-Skid Performance on a Contaminated Runway | AIRBUS CANADA LP BD-500 (A220 Series) | 2025-12-30 | 32 |
| AD | 2025-0292 | 2025-12-19 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | DASSAULT AVIATION Mystère-Falcon 900 | 2026-01-02 | 05 |
| AD | 2025-0291 | 2025-12-19 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | DASSAULT AVIATION Falcon 900EX | 2026-01-02 | 05 |
| AD | 2025-0290 | 2025-12-19 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | DASSAULT AVIATION Falcon 900EX | 2026-01-02 | 05 |
| AD | 2025-0285 | 2025-12-18 | Wings - Main Wing Spar - Inspection | AMS - Flight CARAT A | 2026-01-01 | 57 |
| AD | 2025-0206R1 | 2025-12-18 | Engine - High Pressure Turbine Blades - Inspection | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG TRENT 1000 | 2025-12-25 | 72 |
| AD | 2025-0287 | 2025-12-17 | Powerplant - Fuel Draining System - Inspection | AIRBUS HELICOPTERS AS 355 | 2025-12-31 | 71 |
| AD | 2025-0286 | 2025-12-17 | Aircraft Flight Manual - Emergency Procedure Section - Amendment Master Minimum Equipment List - Amendment Communications - Digital Radio and Audio Integrating Management System - Modification | AIRBUS S.A.S. A330 | 2025-12-31 | 23 |
| AD | 2025-0289 | 2025-12-17 | Wings - Centre Wing Box Fastener Holes at Frame 40 Vertical Web - Inspection | AIRBUS S.A.S. A330 | 2025-12-31 | 57 |
| AD | 2025-0288 | 2025-12-17 | Engine - Low Pressure Compressor Blades - Removal from Service | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG RB211 TRENT 700 | 2025-12-31 | 72 |
| AD | 2025-0284 | 2025-12-16 | Flight Controls - Rudder Control System / Drive - Inspection | AIRBUS DEFENCE & SPACE GmbH BÄřřikow BO 208 BÄřřikow BO 209 | 2025-12-30 | 27 |
| AD | US-2025-25-04 | 2025-12-15 | Equipment / Furnishings - Escape Slide Assembly - Inspection | BOEING 737 | 2026-01-16 | 25 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|---------------|------------|--|---|----------------|-------------|
| AD | US-2025-23-03 | 2025-12-15 | Engine Strut Structure / Thermal Switch - Inspection | BOEING 757 | 2026-01-13 | 26 |
| AD | 2023-0147R2 | 2025-12-15 | Time Limits / Maintenance Checks - Main Gearbox Suspension Bar Pins / Fittings - Recalculation of Life Limits / Replacement / Modification Fuselage - Main Gearbox Suspension Bar Pins / Fittings - Replacement / Modification | AIRBUS HELICOPTERS SA 330 / AS 332 / EC 225 | 2025-12-22 | 05, 53 |
| AD | 2025-0282 | 2025-12-12 | Equipment / Furnishings - Emergency Locator Transmitter - Rotorcraft Flight Manual - Amendment / Operational Restrictions / Modification | GUIMBAL, HELICOPTERES CABRI | 2025-12-19 | 25 |
| AD | 2025-0261R1 | 2025-12-12 | Engine Fuel and Control - Fuel Pump - Replacement | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG TRENT XWB | 2025-12-19 | 73 |
| EAD | 2025-0277-E | 2025-12-11 | Fuselage - Tail boom skin - Inspection | AIRBUS HELICOPTERS EC175 | 2025-12-15 | 53 |
| AD | 2025-0274 | 2025-12-11 | [Correction] Fire Protection - Fire Panel - Inspection | AIRBUS S.A.S. A318 A319 A320 A321 | 2025-12-16 | 26 |
| SD | SD-2025-02R1 | 2025-12-11 | Flight Procedure Design software used in the calculation of final approach minima for non-precision approaches | Safety Directives ATM/ANS | 2025-12-16 | |
| AD | 2025-0280 | 2025-12-11 | Wings - Wing Mid Spars - Inspection | AIRBUS S.A.S. A380 | 2025-12-18 | 57 |
| AD | 2025-0281 | 2025-12-11 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | PILATUS AIRCRAFT LTD PC-6 | 2025-12-25 | 05 |
| AD | 2025-0247R1 | 2025-12-11 | Fuselage - Forward and Aft Cargo Door Piano Hinges - Inspection | AIRBUS S.A.S. A350 | 2025-12-18 | 53 |
| AD | US-2025-23-06 | 2025-12-10 | Fuselage - Attach Fittings and Upper Splice Fitting of the Stub Beam Horizontal Pressure Deck - Inspection | BOEING 787 | 2026-01-13 | 53 |
| AD | US-2025-23-05 | 2025-12-10 | Fuselage - Forward Pressure Bulkhead - Inspection | BOEING 787 | 2026-01-13 | 53 |
| AD | 2025-0279 | 2025-12-10 | Fuselage - Cargo Bay - Inspection | AIRBUS HELICOPTERS H160 | 2025-12-24 | 53 |
| AD | 2025-0276 | 2025-12-10 | Wings - Wing Landing Gear Attachment - Inspection / Repair / Replacement | AIRBUS S.A.S. A380 | 2025-12-24 | 57 |
| AD | CF-2025-66 | 2025-12-09 | Engine - Compressor Turbine (CT) Disk Assembly - Unsubstantiated CT Disk Part Number (P/N) in Engine Technical Publications | PRATT & WHITNEY CANADA PT6T | 2025-12-19 | 72 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|---------------|------------|---|--|----------------|-------------|
| AD | 2025-0275 | 2025-12-09 | Aircraft Flight Manual / Normal Procedure Ground Engine Operation in Icing Condition - Amendment | AIRBUS S.A.S. A319 A320 A321 | 2025-12-23 | |
| AD | CF-2025-65 | 2025-12-09 | Pneumatic - 10th and 14th Stage Bleed Duct Damaged or Missing Insulation | MHI RJ Aviation ULC CL-600 (Regional Jet) | 2025-12-19 | 36 |
| AD | CF-2025-64 | 2025-12-09 | Doors - Sliding Door Lower Roller disengagement | BELL TEXTRON CANADA LTD (BTCL) 429 | 2025-12-15 | 52 |
| AD | 2025-0263 | 2025-12-09 | [Correction] Hydraulic Power - Single Generation Hydraulic System Wiring Diode - Cut-Off Test | AIRBUS HELICOPTERS AS 350 / EC 130 | 2025-12-10 | 29 |
| AD | 2022-0191R1 | 2025-12-09 | Main Rotor Drive - Main Gearbox Oil Cooling Fan - Inspection / Replacement / Modification | AIRBUS HELICOPTERS SA 330 / AS 332 / EC 225 | 2025-12-16 | 65 |
| SIB | 2025-10 | 2025-12-08 | Arriel 1 Engines - Module 03 - TU377 Modification Implementation | SAFRAN HELICOPTER ENGINES ARRIEL 1 Safety Information Bulletin Airworthiness | | |
| AD | 2025-0242 | 2025-12-08 | [Correction] Rotorcraft Flight Manual - Emergency Procedures Section - Amendment Integrated Modular Avionics - Ethernet Network - Inspection / Modification | AIRBUS HELICOPTERS H160 | 2025-11-11 | 42 |
| AD | 2025-0205R3 | 2025-12-08 | Fuselage - Passenger Seat Tracks - Inspection / Replacement | ATR ATR42 ATR72 | 2025-12-15 | 53 |
| AD | CF-2025-62 | 2025-12-05 | Fuselage - Tailboom - Elongated Holes and Gaps on Tailcone Assembly | BELL TEXTRON CANADA LTD (BTCL) (Jet Ranger X) 505 | 2025-12-12 | 53 |
| AD | 2025-0254R1 | 2025-12-05 | Wing - Main Landing Gear Retraction Actuator Fitting - Inspection | AIRBUS S.A.S. A320 A321 | 2025-12-08 | 57 |
| AD | US-2025-21-02 | 2025-12-03 | Flight Controls - Non-Essential Gust Suppression Function - Disable | BOEING 777 | 2026-01-02 | 27 |
| AD | 2025-0272 | 2025-12-02 | Airborne Auxiliary Power - Air Intake Flap Hinge - Inspection Master Minimum Equipment List - Amendment | AIRBUS S.A.S. A350 | 2025-12-16 | 49 |
| AD | 2025-0271 | 2025-12-02 | Central Maintenance System - Central Computer / Primus APEX Operational Software - Modification | PILATUS AIRCRAFT LTD PC-12 | 2025-12-16 | 45 |
| AD | 2025-0273 | 2025-12-02 | Rotors Flight Control - Tail Rotor Pedals Support Bracket - Inspection | MECAER AVIATION GROUP SpA AMD-500N NH-500D | 2025-12-16 | 67 |
| AD | 2025-0270 | 2025-12-02 | Wings - Leading Edge Devices / Slats and Droop Noses - Identification | AIRBUS S.A.S. A380 | 2025-12-16 | 57 |
| AD | CF-2025-51R1 | 2025-12-02 | Flight Controls - Uncommanded and Unarrested Flap Movement | BOMBARDIER CL-600 (Challenger) | 2025-12-12 | 27 |
| AD | 2006-0085R3 | 2025-12-02 | Landing Gear - Main Landing Gear Shock Strut Cylinder - Inspection / Replacement / Modification | DAHER AEROSPACE TBM 700 | 2025-12-09 | 32 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|-----------------|------------|--|--|----------------|-------------|
| AD | CF-2025-61 | 2025-12-01 | Wing - Slat Track Corrosion and Wear | AIRBUS CANADA LP BD-500 (A220 Series) | 2025-12-08 | 57 |
| AD | US-2025-21-05 | 2025-12-01 | Landing Gear - Upper Lock Link Assembly - Inspections | BOEING 717 | 2026-01-02 | 32 |
| AD | US-2025-20-14 | 2025-12-01 | Equipment / Furnishings - IPECO 3A090 and 3A258 Flight Crew Seats - Inspection | BOEING 757 | 2026-01-02 | 25 |
| AD | CF-2025-63 | 2025-12-01 | Flight Controls - Elevator Control System - Autopilot Control Cable Failure | MHI RJ Aviation ULC CL-600 (Regional Jet) | 2025-12-01 | 27 |
| AD | 2025-0269 | 2025-12-01 | Windows - Jettisonable Window System Elements - Inspection / Lubrication / Replacement | AIRBUS HELICOPTERS AVIATION GROUP SpA 10080809 H160MECAER EASA STC | 2025-12-15 | 56 |
| EAD | 2025-0268-E | 2025-11-28 | Flight Controls - Elevator Aileron Computer - Replacement | AIRBUS S.A.S. A319 A320 A321 | 2025-11-29 | 27 |
| EAD | 2025-0267-E | 2025-11-28 | Engine - Propeller Gearbox - Inspection | BRP-ROTAX GmbH & Co KG 915 916 iSc | 2025-12-02 | 72 |
| SIB | 2025-09 | 2025-11-28 | Potential de-/anti-icing fluids offered at European airports not-fully conforming to their initial qualification | Safety Information Bulletin Airworthiness Operations | | |
| AD | US-2025-24-02 | 2025-11-28 | Landing Gear - Main Landing Gear Brake Hydraulic Hoses - Inspection | BOEING 737 | 2025-12-10 | 32 |
| AD | 2025-0265 | 2025-11-28 | Air - Intermediate / High Pressure Air Tubes - Inspection | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG TRENT 7000 | 2025-12-12 | 75 |
| AD | 2025-0266 | 2025-11-28 | Engine - High Pressure Turbine Blades - Inspection | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG TRENT 7000 | 2025-12-12 | 72 |
| AD | BR-2018-07-01R2 | 2025-11-27 | Landing Gear - Pintle Pins of the Main Landing Gear Shock Struts - Inspection | EMBRAER S.A. ERJ 190 | 2025-11-26 | 32 |
| AD | 2025-0264 | 2025-11-26 | Main Rotor - Scissors Spherical Bearings - Inspection | AIRBUS HELICOPTERS H160 | 2025-12-10 | 62 |
| AD | US-2025-23-53 | 2025-11-26 | Nacelles / Pylons - Suspension of Flight Operations | BOEING DC-10 MD-10 MD-11 | 2025-12-01 | 54 |
| AD | 2023-0073R2 | 2025-11-26 | Electrical Power - DC Starter Generator - Inspection | SAAB AB 340 | 2025-12-03 | 24 |
| EAD | 2025-0262-E | 2025-11-25 | Tail Rotor Drive - Centre Shaft Assembly - Inspection / Replacement / Life Limitations | AIRBUS HELICOPTERS AS 350 / EC 130 | 2025-11-27 | 65 |
| AD | 2025-0260 | 2025-11-25 | Rotors Flight Control - Ball Bearing Control System - Inspection | AIRBUS HELICOPTERS DEUTSCHLAND EC135/635 | 2025-12-02 | 67 |
| AD | 2025-0259 | 2025-11-24 | Pneumatic - Trent XWB Engine Bleed Air Supply System T-Duct - Replacement | AIRBUS S.A.S. A350 | 2025-12-08 | 36 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|---------------|------------|---|---|----------------|-------------|
| AD | 2025-0251 | 2025-11-24 | Structure - Structural Parts - Replacement / Inspection | AIRBUS S.A.S. A330ELBE FLUGZEUGWERKE GmbH EASA STC 10063798 | 2025-12-08 | 53 |
| AD | CF-2025-21R1 | 2025-11-24 | Main Rotor - Expandable Blade Bolt incorrect heat treatment | BELL TEXTRON CANADA LTD (BTCL) 407 427 | 2025-12-01 | 62 |
| AD | 2021-0291R2 | 2025-11-24 | Doors - Passenger Door Stop Screw - Inspection | AIRBUS S.A.S. A350 | 2025-12-01 | 52 |
| AD | 2025-0257 | 2025-11-21 | Engine - Rear Engine Mount Screws - Inspection | CONTINENTAL AEROSPACE TECHNOLOGIES, GmbH CENTURION 3.0 | 2025-11-28 | 72 |
| AD | 2025-0258 | 2025-11-21 | Landing Gear - Nose Landing Gear Sliding Tube - Inspection | AIRBUS S.A.S. A318 A319 A320 A321 | 2025-12-05 | 32 |
| AD | CF-2025-59 | 2025-11-20 | Fuselage - Tailboom - Tailboom Attachment Hardware Fracture | BELL TEXTRON CANADA LTD (BTCL) 407 | 2025-12-03 | 53 |
| AD | CF-2025-57 | 2025-11-20 | Stabilizers - Vertical Stabilizer Leading Edge Missing Clad Material | BOMBARDIER BD-700 | 2025-11-26 | 55 |
| AD | CF-2025-56 | 2025-11-20 | Equipment/Furnishings - Structural Degradation of Galley Panel Assemblies | BOMBARDIER BD-700 | 2025-11-26 | 25 |
| AD | 2025-0256 | 2025-11-20 | Wings - Centre Wing Box Frame 47 Angle Fittings - Inspection / Modification | AIRBUS S.A.S. A300-600ST (Beluga) | 2025-12-04 | 57 |
| AD | CF-2023-38R1 | 2025-11-20 | Time Limits/Maintenance Checks - Introduction & Revision of the Airworthiness Limitations | BOMBARDIER BD-700 | 2025-11-27 | 05 |
| AD | 2018-0229R1 | 2025-11-20 | Wings - Centre Wing Box Frame 47 Angle Fittings - Inspection / Modification | AIRBUS S.A.S. A300-600 | 2025-12-04 | 57 |
| AD | 2025-0255 | 2025-11-19 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 / Damage Tolerant Airworthiness Limitations Items - Amendment | AIRBUS S.A.S. A300-600 | 2025-12-03 | 05 |
| AD | 2025-0253 | 2025-11-14 | SUPERSEDED BY EASA AD 2025-0274 | AIRBUS S.A.S. A318 A319 A320 A321 | 2025-11-21 | 26 |
| AD | CF-2025-58 | 2025-11-14 | Time Limits/Maintenance Checks (TLMC) - Airworthiness Limitations (AWL) | BOMBARDIER BD-100 | 2025-12-13 | 05 |
| AD | US-2025-23-51 | 2025-11-14 | SUPERSEDED BY FAA AD 2025-23-53 | BOEING MD-11 | 2025-12-01 | 54 |
| AD | 2025-0252 | 2025-11-14 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 / Damage Tolerant Airworthiness Limitations Items - Amendment | AIRBUS S.A.S. A380 | 2025-11-28 | 05 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|--------------|------------|--|--|----------------|-------------|
| AD | CF-2025-55 | 2025-11-12 | Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in Canadian airspace | DE HAVILLAND AIRCRAFT OF CANADA LTD. DHC-8 | 2025-11-19 | 34 |
| AD | CF-2025-54 | 2025-11-12 | Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in Canadian airspace affected by 5G C-Band wireless signals | DE HAVILLAND AIRCRAFT OF CANADA LTD. DHC-8 | 2025-11-19 | 34 |
| AD | CF-2025-53 | 2025-11-10 | Flight Controls - Incorrect Airplane Flight Manual (AFM) Approach Speed Adder and Landing Distance Factors for SLAT FAIL (Caution) Crew-Alerting System (CAS) Message Non-Normal Procedure | BOMBARDIER BD-700 | 2025-11-19 | CF-2025-53 |
| AD | 2025-0250 | 2025-11-10 | Fuselage - Frame Inboard Boom - Inspection | FOKKER SERVICES F28 | 2025-11-24 | 53 |
| AD | CF-2024-22R1 | 2025-11-10 | Navigation - Required Navigation Performance Authorization Required (RNP-AR) Approach Vertical Deviation | BOMBARDIER BD-700 | 2025-11-21 | 34 |
| EAD | 2025-0249-E | 2025-11-07 | SUPERSEDED BY EASA EMERGENCY AD 2025-0262-E | AIRBUS HELICOPTERS AS 350 / EC 130 | 2025-11-11 | 65 |
| AD | 2025-0248 | 2025-11-06 | Equipment / Furnishings - Overhead Stowage Compartments - Inspection / Repair | AIRBUS S.A.S. A318 A319 A320 A321 | 2025-11-20 | 25 |
| SIB | CASA-2025-11 | 2025-11-03 | Part Number MS20220-3 Pulleys with Corroded and Dislodged Bearings | DE HAVILLAND AIRCRAFT OF CANADA LTD. DHC-8 Safety Information Bulletin Airworthiness | | |
| AD | CF-2025-52 | 2025-10-31 | Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in the contiguous United States of America (U.S.) airspace. | DE HAVILLAND AIRCRAFT OF CANADA LTD. DHC-8 | 2025-11-06 | 34 |
| ADR | 2025-0026R1 | 2025-10-31 | Oxygen - Full-Face Quick Donning Masks - Functional Check | AIRBUS MILITARY SL A400M | | 35 |
| AD | 2025-0244 | 2025-10-30 | Doors - Passenger / Crew Door Girt Bar Fitting Assemblies - Inspection | AIRBUS S.A.S. A350 | 2025-11-13 | 52 |
| AD | 2025-0245 | 2025-10-30 | Fire Protection - Pyrotechnical Cartridge - Inspection | DASSAULT AVIATION Fan Jet Falcon Mystère-Falcon 20 Mystère-Falcon 20GF/200 | 2025-11-13 | 26 |
| AD | 2025-0246 | 2025-10-30 | Engine - Non-Synchronous Vibration During Engine Operation - Monitoring / Replacement | CFM INTERNATIONAL LEAP-1A/-1C | 2025-11-13 | 72 |
| AD | 2025-0207R1 | 2025-10-30 | Fuselage - Seat Rail Connections Nylon Bushes - Replacement | AIRBUS S.A.S. A318 A319 A320 A321 | 2025-11-06 | 53 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|---------------|------------|---|---|----------------|-------------|
| AD | 2025-0238 | 2025-10-30 | [Correction] Electrical Power - Ram Air Turbine - Replacement | AIRBUS S.A.S. A350 | 2025-11-10 | 24 |
| AD | US-2025-19-12 | 2025-10-29 | Landing Gear - Main Landing Gear Outer Cylinders - Records Check / Inspection | BOEING 737 | 2025-11-06 | 32 |
| AD | 2025-0137 | 2025-10-29 | [Correction] Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | AIRBUS HELICOPTERS AS 350 / EC 130 | 2025-07-11 | 04 |
| AD | 2025-0241 | 2025-10-29 | Navigation - Angle of Attack Backplate - Repair | AIRBUS S.A.S. A330 A340 | 2025-11-12 | 34 |
| AD | 2025-0243 | 2025-10-28 | Engine - Forward Outer Seal, High-Pressure Compressor Stages 6-10 Compressor Rotor Spools and High-Pressure Turbine Rotor Stage 1 Disks - Replacement | CFM INTERNATIONAL LEAP-1A/-1C | 2025-11-11 | 72 |
| AD | 2025-0223R1 | 2025-10-28 | Parking, Mooring and Storage - Mooring Procedure - Prohibition | ATR ATR42 ATR72 | 2025-10-29 | 10 |
| AD | 2022-0168R2 | 2025-10-28 | Rotorcraft Flight Manual - Section Emergency Procedures - Amendment Integrated Modular Avionics - Ethernet Network - Inspection | AIRBUS HELICOPTERS DEUTSCHLAND EC135/635 MBB-BK 117 | 2025-11-11 | 42 |
| AD | 2025-0240 | 2025-10-27 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2, Airworthiness Limitation Items and Safe Life Items - Amendment | FOKKER SERVICES F27 | 2025-11-10 | 05 |
| AD | 2025-0237 | 2025-10-27 | Equipment / Furnishings - 80 VU Rack Attachments - Inspection / Repair | AIRBUS S.A.S. A318 A319 A320 A321 | 2025-11-10 | 25 |
| AD | 2025-0239 | 2025-10-27 | Rotors Flight Control - Upper Ball Bearing End of the Main Rotor Servo-Controls - Inspection | AIRBUS HELICOPTERS SA/AS 365 / EC 155 | 2025-11-10 | 67 |
| AD | 2025-0235 | 2025-10-23 | Engine - Vibration Levels - Measurements / Inspections | WSK PZL-SWIDNIK S.A. PZL W-3A | 2025-11-06 | 72 |
| AD | 2025-0233 | 2025-10-23 | Engine - High-Pressure Compressor / Mini-Disc Anti-Rotation Block - Inspection / Modification | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG TRENT 1000 | 2025-11-06 | 72 |
| AD | 2025-0234 | 2025-10-23 | SUPERSEDED BY EASA AD 2025-0253 | AIRBUS S.A.S. A318 A319 A320 A321 | 2025-11-06 | 26 |
| AD | 2025-0236 | 2025-10-23 | Fuselage - Frame Base Fitting between Frames 41 and 46 - Inspection / Repair | AIRBUS S.A.S. A300-600 | 2025-11-06 | 53 |
| AD | 2025-0232 | 2025-10-22 | Wings - Centre Section Frame 40 Forward Fitting Radius at Tension Bolt Junction - Inspection / Repair | AIRBUS S.A.S. A300-600ST (Beluga) | 2025-11-05 | 57 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|--------------------|------------|--|--|----------------|-------------|
| AD | BR-2025-09-02 | 2025-10-22 | [Correction] Airworthiness Limitations (Certification Maintenance Requirements, Airworthiness Limitation Inspections, Fuel System Limitation Items, and Life Limited Items) - Revision | EMBRAER S.A. EMB-135 | 2025-09-15 | |
| SIB | 2023-03R1 | 2025-10-22 | Incorrect Barometric Altimeter Setting | Safety Information Bulletin ATM/ANS Operations | | |
| AD | 2019-0044R1 | 2025-10-22 | Wings - Centre Section Frame 40 Forward Fitting Radius at Tension Bolt Junction - Inspection / Repair | AIRBUS S.A.S. A300-600 | 2025-11-05 | 57 |
| AD | 2025-0231 | 2025-10-21 | Fire Protection - Pyrotechnical Cartridge - Inspection | AIRBUS HELICOPTERS SA 330 / AS 332 / EC 225 | 2025-11-04 | 26 |
| EAD | 2025-0230-E | 2025-10-21 | Powerplant - Turbocharger and Intercooler Hoses - Inspection/Replacement | SMA AERO ENGINES GmbH EASA STC 10013975 EASA STC 10016495 STC EASA IM.A.S.02857 STC EASA.A.S.00774TEXTRON AVIATION INC. 182 (Skylane) F182 | 2025-10-23 | 71 |
| SIB | 2025-08 | 2025-10-20 | Failure of the Digital Radio and Audio Integrated Management System on the Airbus A320 NEO and A330 Family Aeroplanes | AIRBUS S.A.S. A320 A330Safety Information Bulletin ATM/ANS Operations | | |
| AD | 2025-0229 | 2025-10-20 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment | DASSAULT AVIATION Falcon 7X | 2025-11-03 | 05 |
| AD | 2021-0281R3 | 2025-10-20 | Aircraft Flight Manual / Engine Bleed Air System - Amendment / Pneumatic - Engine Bleed Air System - Maintenance Tasks | AIRBUS S.A.S. A330 | 2025-10-27 | 36 |
| ADR | 2025-0226 | 2025-10-16 | Engine - Propeller Gear Box / Referenced Flight Cycles - Recalculation / Replacement | EPI EUROPROP INTERNATIONAL GmbH TP400-D6 | | 72 |
| AD | ISR-I-05-2025-10-1 | 2025-10-16 | G150 Airworthiness Limitations Section Revision | GULFSTREAM (GALP) G150 | 2025-10-31 | |
| AD | 2025-0227 | 2025-10-16 | Main Rotor - Upper and Lower H Legs - Service Life Limit | AIRBUS HELICOPTERS EC175 | 2025-11-13 | 62 |
| SIB | SAIB-2025-10 | 2025-10-16 | Propeller Controlling System | HAMILTON SUNDSTRAND 247FSafety Information Bulletin Airworthiness | | |
| EAD | 2025-0225-E | 2025-10-16 | SUPERSEDED BY EASA EMERGENCY AD 2025-0230-E | SMA AERO ENGINES GmbH EASA STC 10013975 STC EASA.A.S.00774TEXTRON AVIATION INC. 182 (Skylane) F182 | 2025-10-20 | 71 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|---------------|------------|--|---|----------------|-------------|
| AD | 2025-0224 | 2025-10-16 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 / Damage Tolerant Airworthiness Limitations Items - Amendment | AIRBUS S.A.S. A310 | 2025-10-30 | 05 |
| AD | 2007-0201R1 | 2025-10-16 | Engine - High Pressure and Intermediate Pressure Turbine Bearing Oil Vent Tubes - Inspection / Cleaning / Replacement | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG RB211 TRENT 700 | 2025-10-23 | 72 |
| AD | 2025-0222 | 2025-10-13 | AEROSPACE & DEFENSE OXYGEN SYSTEMS SaS (Part of SAFRAN AEROSYSTEMS): Portable Breathing Equipment - Operational Instructions | APPLIANCES ATA 35 OXYGEN | 2025-10-20 | 35 |
| AD | CF-2025-50 | 2025-10-13 | Flight Controls - Roll Control Input-Modules (RCIMs) Incorrect Installation | BOMBARDIER BD-700 | 2025-10-22 | 27 |
| SIB | 2025-07 | 2025-10-13 | Continuous Use of Stop Bars | Safety Information Bulletin Aerodromes ATM/ANS | | |
| AD | CF-2025-49 | 2025-10-13 | Wings - Low Clearance Between Fuel Vent Tube Installation and Surrounding Systems and Structures in Right Wing | BOMBARDIER BD-700 | 2025-10-15 | 57 |
| EAD | 2025-0221-E | 2025-10-10 | Flight Controls - Rudder Control System / Bracket to Frame 29 - Inspection | POLSKIE ZAKLADY LOTNICZE (PZL) MIELEC M28 | 2025-10-15 | 27 |
| AD | US-2025-18-02 | 2025-10-10 | Oxygen - Passenger Service Unit Oxygen Panel Assemblies - Inspection | BOEING 787 | 2025-10-22 | 35 |
| AD | 2025-0220 | 2025-10-10 | Flight Manual - Amendment Powerplant - Operational Restriction Placards and Markings - Placards - Installation | DG AVIATION GmbH DG-1000 | 2025-10-24 | 11, 71 |
| SIB | BEA-2025-02 | 2025-10-09 | Fire Protection - Tube Replacement | EMBRAER S.A. ERJ 190 Safety Information Bulletin Airworthiness | | |
| AD | US-2025-20-11 | 2025-10-09 | Flight Controls - Attaching Rivets of the Pilot and Copilot Rudder Control Pushrods - Inspection | TEXTRON AVIATION INC. 200 (Super King Air) 300 (Super King Air) | 2025-10-17 | 27 |
| AD | US-2025-20-04 | 2025-10-09 | Flight Controls - Aileron Trim Actuator - Repetitive Inspections / Modification | BOEING 757 | 2025-11-06 | 27 |
| AD | US-2025-20-03 | 2025-10-09 | Equipment / Furnishings - Lower Fitting Assemblies and Centerline Partition Threshold of Lavatories - Inspection / Revision of Maintenance Program | BOEING 787 | 2025-11-06 | 25 |
| AD | US-2025-19-11 | 2025-10-09 | Landing Gear - Main Landing Gear Outer Cylinders - Records Check / Inspection | BOEING 757 | 2025-11-06 | 32 |



| AD class | AD number | Issue Date | Subject | Approval Holder / Type Designation | Effective date | ATA Chapter |
|----------|---------------|------------|--|--|----------------|-------------|
| AD | US-2025-17-11 | 2025-10-09 | Rotors Flight Control - Tail Rotor Pedal Support Brackets - Repetitive Inspections | MD HELICOPTERS INC (MDHI) 369 500N 600N | 2025-10-10 | 67 |
| AD | BR-2025-10-01 | 2025-10-09 | Engine Feed Check Valve - Inspections / Functional Test | EMBRAER S.A. ERJ 190 | 2025-10-09 | |
| AD | 2025-0218 | 2025-10-06 | Equipment / Furnishings - Emergency Location Transmitter Mounting Tray - Replacement | AIRBUS HELICOPTERS H160 | 2025-10-20 | 25 |
| AD | 2025-0219 | 2025-10-06 | SUPERSEDED BY EASA AD 2026-0035 | AIRBUS S.A.S. A330 | 2025-10-20 | 05 |
| AD | 2025-0216 | 2025-10-01 | Equipment / Furnishings - Doghouse Placard - Replacement | AIRBUS S.A.S. A330 A340 | 2025-10-15 | 25 |
| AD | 2025-0217 | 2025-10-01 | Rotors Flight Control - Fork Lever - Inspection | AIRBUS HELICOPTERS DEUTSCHLAND BO 105 EASA STC 10039633 MBB-BK 117 | 2025-10-15 | 67 |
| AD | 2025-0215 | 2025-10-01 | Stabilizers - Vertical Stabilizer to Rudder Junction Ribs and Lugs -Inspection / Replacement (Wrong Material) | ATR ATR42 ATR72 | 2025-10-15 | 55 |
| AD | 2025-0214 | 2025-09-30 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Part 2 / Damage Tolerant Airworthiness Limitation Items - Amendment | AIRBUS S.A.S. A300-600 | 2025-10-14 | 05 |
| AD | 2025-0200 | 2025-09-30 | [Correction] Equipment / Furnishings - Passenger Seats - Modification | DASSAULT AVIATION Falcon 2000 Falcon 7X Falcon 900EX Mystère-Falcon 900 | 2025-10-01 | 25 |
| AD | 2025-0213 | 2025-09-26 | SUPERSEDED BY EASA AD 2026-0072 | LEONARDO S.p.A. HELICOPTERS AW189 | 2025-10-10 | 71 |
| AD | US-2025-19-13 | 2025-09-26 | Engine - High-Pressure Turbine 1st-stage and 2nd-stage Hubs - Replacement | INTERNATIONAL AERO ENGINES AG V2500-()5 | 2025-10-29 | 72 |
| AD | G-2025-0005 | 2025-09-26 | ACRO AIRCRAFT SEATING LIMITED: Series 9 Passenger Seats - Modification | APPLIANCES ATA 25 EQUIPMENT / FURNISHINGS | 2025-10-02 | 25 |