

COMMENT RESPONSE DOCUMENT

EASA PAD No. 22-035

[Published on 28 March 2022 and officially closed for comments on 25 April 2022]**Commenter 1: Deer Jet – 李飞 Philip – 12/04/2022****Comment # 1**

In the paragraph (7), during the measurement as required by paragraph (1),

But the paragraph (1) is for inspection, not measurement. So that should be paragraph (2)?

(7) If, during the measurement as required by paragraph (1) of this AD, a clearance of more than 1 mm but equal to or less than 13 mm is detected, before next flight install ROUNDIT2000NX sheath using white binding braid in accordance with the instructions of the inspection SB.

EASA response:

We agree: The Corrective Action referenced in paragraph (7) is related to the measurement of the clearance between the two electrical power feeders and the forward lavatory bulkhead final AD. The final AD is updated accordingly.

