Publ. number	Issue Date	TC Holder	Type	Subject
US-2026-20-14	2026-10-21	BOEING	737	Stabilizers - Horizontal Stabilizer Pivot Hinges and Jackscrew
US-2026-20-13	2026-10-21	BOEING	737	Equipment/Furnishings - Passenger Service Unit-Mounted Video Monitors - Replacement
US-2026-20-04	2026-10-21	BOEING	757	Fuselage - Cracks Frames Around Uppermost Fastener - Inspection
US-2026-21-06	2026-10-20	PRATT & WHITNEY	PW4000	Engine Fuel and Control - Pressure Burner Sensors - Replacement
2026-0199	2026-10-20	ALLSTAR PZL GLIDER	SZD-54 Perkoz	Flight Controls - Airbrake Control Torsion Tube - Inspections
2026-0200	2026-10-20	AIRBUS S.A.S.	A330	Landing Gear - Tachometer Wiring Harness - Modification
2026-0198	2026-10-19	AIRBUS HELICOPTERS, MECAER AVIATION GROUP SpA	H160, EASA STC 10080809	Doors - Emergency Exit Rope on the Jettisonable Window Systems - Cleaning
US-2026-20-10	2026-10-19	BOEING	787	Flight Controls - Leading Edge Outboard Slat Systems - Airplane Flight Manual - Amendment
2025-0159R1	2026-10-19	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355, EC 120 B	Placards and Markings - Unlock Sliding Door - Installation
US-2026-20-01	2026-10-16	BOEING	787	Fuselage - Cargo Liner Joint Sealing Tape - Inspection
2026-0197	2026-10-16	SCHEMPP HIRTH FLUGZEUGBAU	Ventus Powered Sailplanes	Electrical Power - Charge Controller - Modification
2026-0177R1	2026-10-15	AIRBUS S.A.S.	A350	Indicating / Recording Systems - Integrated Control Panels - Inspection
2026-0195	2026-10-13	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	Tail Rotor Drive - Tail Gear Box Control Rod Bearings - Replacement / Life Limitation
2026-0196	2026-10-13	AIRBUS HELICOPTERS	H160	Equipment / Furnishings - System Interface Unit - Replacement
CF-2026-47R1	2026-10-13	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Wing - Wing Access Panels with Un-trimmed Stiffeners and/or Reduced Thickness - Inspection
US-2026-20-12	2026-10-12	ENGINE ALLIANCE LLC	GP7200	Turbine - High-Pressure Turbine Interstage Seal - Replacement
US-2026-19-04	2026-10-12	BOEING	777	Hydraulic Power - Alternating Current Motor Pump - Inspection
CF-2026-50	2026-10-12	BELL TEXTRON CANADA LTD (BTCL)	429	Tail Rotor - Tail Rotor Pitch Link Spherical Bearing Missing Hard Coating - Inspection

Publ. number	Issue Date	TC Holder	Type	Subject
2026-0194	2026-10-12	AIRBUS S.A.S., ELBE FLUGZEUGWERKE GmbH	A330, EASA STC 10063798	Aircraft Flight Manual Supplement - Abnormal Procedures - Amendment
CF-2026-49	2026-10-12	AIRBUS CANADA LP	BD-500 (A220 Series)	Engine Controls - Throttle Quadrant Assembly - Throttle Lever Jamming - Replacement