Publ. number	Issue Date	TC Holder	Type	Subject
2026-0143R1	2026-11-06	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000, TRENT 7000	Engine - Intermediate Pressure Compressor Shaft Assembly / Front Air Seal - Inspection
2026-0215	2026-11-06	ATR	ATR42, ATR72	Oxygen - Oxygen Pressure Regulator - Inspection
2026-0202R1	2026-11-06	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Stabilizers - Vertical Fin - Inspection / Modification Placards and Markings - Interior Placards - Installation Aircraft Flight Manual / Airspeed Limitations - Amendment
2026-0203	2026-11-05	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000	[Correction] Engine - High Pressure Turbine Blades - Inspection
2026-0214	2026-11-05	AIRBUS S.A.S.	A350	Electrical Power - Emergency Electrical Network Management Unit - Modification / Re-Identification
2026-0211	2026-11-04	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Fire Protection - Pyrotechnical Cartridge - Inspection
2026-0213	2026-11-04	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuselage - Mid Avionics Bay - Modification
2026-0212	2026-11-04	DAHER AIRCRAFT, SAS	TBM 700	Landing Gear - Main Landing Gear Barrel - Inspection
2026-0209	2026-11-03	AIRBUS S.A.S.	A300-600, A300-600ST (Beluga), A310	Wings - Main Landing Gear Attachment / Rib 5 Forward Lug - Inspection(s)
CF-2026-53	2026-11-03	AIRBUS CANADA LP	BD-500 (A220 Series)	Powerplant - A220 Freezing Fog Limitation - Implementation / Amendment
CF-2026-54	2026-11-03	AIRBUS CANADA LP	BD-500 (A220 Series)	Air Conditioning - Outflow Valve Manual Mode Direct Current Motor Failure - Amendment
US-2026-21-12	2026-11-03	BOEING	757	Equipment/Furnishings - Passenger Service Unit-Mounted Video Monitors - Replacement
CF-2026-56	2026-11-03	BELL TEXTRON CANADA LTD (BTCL)	429	Rotors Flight Control - Reduced AFT Cyclic Stick Margin - Replacement
2026-0210	2026-11-03	AIRBUS S.A.S.	A350	Stabilizers - Trimmable Horizontal Stabilizer Centre Joint Pivot Fitting - Inspections
2026-0207	2026-11-02	DG AVIATION GmbH	DG-500, DG-800	Fuel - Hoses - Inspection / Replacement
CF-2026-55	2026-11-02	AIRBUS CANADA LP	BD-500 (A220 Series)	Wings - Potential Incorrect Sealant Application on Lower Stabilizer Fitting Bolts - Inspection
CF-2026-57	2026-11-02	DIAMOND AIRCRAFT INDUSTRIES, INC.	DA 40	Electrical Power - Voter Switch Cycling while Restarting the Engine - Airplane Flight Manual - Amendment
CF-2026-52	2026-10-30	BELL TEXTRON CANADA LTD (BTCL)	429	Main Rotor Drive System - Radial Machining Marks on the Surface of the Mast Inner Diameter - Inspection / Replacement

Publ. number	Issue Date	TC Holder	Type	Subject
US-2026-21-13	2026-10-30	ONTIC ENGINEERING AND MANUFACTURING, INC.	SA226, SA227	Flight Controls - Pitch Trim Actuator - Inspection
2026-0206	2026-10-30	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Main Rotor - Rotating Swashplate Yokes - Inspection / Restoration / Service Life Limit
2026-0205	2026-10-30	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Equipment / Furnishings - System Interface Unit - Replacement
2026-0015R1	2026-10-30	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Stabilizers - Horizontal Stabilizer - Inspections
2026-0204	2026-10-29	LEONARDO S.p.A. HELICOPTERS	AW189	Tail Rotor - Damper Bracket - Inspection
BR-2026-10-01	2026-10-26	EMBRAER	EMB-505 (Phenom 300)	Rudder Trim Control System - Inspection / Replacement
US-2026-20-16	2026-10-26	BOEING	787	Powerplant - Right Engine Fan Cowl - Inspection
CF-2026-51	2026-10-26	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Wing - Spoiler - Power Control Unit - Attachment Bracket Separation - Inspection/Replacement
2026-0201	2026-10-26	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Landing Gear - Emergency Flotation System Adhesive Label - Removal