

Airworthiness Directive

86-189 MBB

Date of issue:
September 29, 1986

Affected helicopter:
German Type Certificate No. 3049
MBB-BK 177
All helicopters MBB-BK117-A-1

Subject:
Accessory Replacement Record
List of Time Change Items (TCI)

Reason:
Introduction of retirement time limits.

Action and compliance:
Proceed in accordance with MBB ASB until December 1986.

Technical publication of the manufacturer:
MBB-BK117, Alert Service Bulletin No. ASB-MBB-BK117-10-100 of July 7, 1986,
which becomes herewith part of this AD and may be obtained from
Messrs. MBB-UH, Postfach 801160, D-8000 München 80, Federal Republic of Germany.

Accomplishment and log book entry:
Action to be accomplished by a skilled person and to be checked and entered
in the helicopter's log by a licensed inspector.