

Airworthiness Directive

86-190 MBB

Date of issue:

September 29, 1986

Affected helicopter:

German Type Certificate No. 3049

MBB BK-117

All helicopters equipped with Fire Extinguishing System

P/N 117-75201-01.

Subject:

Check Tee Valve 35200100

Reason:

Possibility of a manufacturing defect.

Action and compliance:

Action to be accomplished in accordance with MBB ASB before reaching 50 flight hours after the effective date of this AD, unless already accomplished.

Technical publication of the manufacturer:

MBB-BK 117 Alert Service Bulletin No. ASB-BK117-70-100

of August 11, 1986

which becomes herewith part of this AD and may be obtained from Messrs. Messerschmitt-Bölkow-Blohm GmbH, Unternehmensbereich Hubschrauber, Postfach 801160, D-8000 München 80, Federal Republic of Germany.

Accomplishment and log book entry:

Action to be accomplished by an approved service Station and to be checked and entered in the helicopter's log by a licensed inspector.