

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 91-227-021(B) R1
In case of any difficulty, reference should be made to the French original issue.

AIRBUS INDUSTRIE

A320 aircraft

Pitot tubes

The present Airworthiness Directive applies to AIRBUS INDUSTRIE A320 aircraft, MSN 002 to 122, 124 to 179, 183 to 194, 196 to 228, 230 to 245 and 247 to 255 included without AIRBUS INDUSTRIE Service Bulletin A320-34-1024 R3.

In order to prevent wrong speed indication - one or several speed indications lower than the real aircraft speed - due to water accumulation in flexible hoses between pitot tubes and air data modules (ADM), the following measure is rendered mandatory on the effective date of this Airworthiness Directive :

- accomplish AIRBUS INDUSTRIE Service Bulletin A320-34-1024 R3 at first opportunity or before January 31, 1992 at the latest.

Ref. : AIRBUS INDUSTRIE Service Bulletin A320-34-1024 R3

EFFECTIVE DATE : JANUARY, 03 1992

e/C

December 24, 91

AIRBUS INDUSTRIE
A320 aircraft

91-227-021(B) R1