

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 93-032-142(B)  
In case of any difficulty, reference should be made to the French original issue.

## AIRBUS INDUSTRIE

### A300 Airplanes

Generator control unit - Protective cover

The present Airworthiness Directive applies to AIRBUS INDUSTRIE A300 aircraft, all certified models excluding A300-600, all serial numbers, on which the modification 10361 has not been incorporated (AIRBUS INDUSTRIE Service Bulletin A300-24-0082).

In order to prevent foreign liquid from entering the generator control unit and causing internal short circuits, the following measures are rendered mandatory at the effective date of this Airworthiness Directive :

- Unless already accomplished and before the December 31, 1993, install a protective cover above each generator control unit as per AIRBUS INDUSTRIE Service Bulletin A300-24-0082 (AIRBUS modification 10361).
- Any alternate means of compliance to this Airworthiness Directive is acceptable, provided it is approved by the local Airworthiness Authority.

**NOTE** : It is suggested to start engines immediately after embodiment, in order to check good connecting of generators.

Ref. : AIRBUS INDUSTRIE Service Bulletin A300-24-0082

**EFFECTIVE DATE : MARCH 27, 1993**

n/C

March 17, 1993

AIRBUS INDUSTRIE  
A300 Airplanes

93-032-142(B)