

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 94-169-161(B) R1
In case of any difficulty, reference should be made to the French original issue.

AIRBUS INDUSTRIE

A300-600 ; A310 Aircraft

Smoke detection in lavatories

This Airworthiness Directive applies to AIRBUS INDUSTRIE A310 and A300-600 aircraft, all certified models, without application of the modification 10156.

In order to detect incorrect installation of the lavatory air extraction duct grill, which could reduce the performance of the smoke detection system, the following measures are rendered mandatory on the effective date of this Airworthiness Directive :

- Within 450 flight hours, unless already accomplished, carry out a one time check, on each lavatory, for correct installation of the air extraction duct grille in accordance with the instructions of A.O.T. AIRBUS INDUSTRIE AOT 26-12 dated June 06, 1994.

NOTA : Any detection system which has been installed by a company, and which does not use the lavatory extraction air system to supply the smoke detector installed, may not be concerned by this CN.

In this particular case inform in writing the local authority of the non applicable status of this airworthiness directive.

Ref. : A.O.T. AIRBUS INDUSTRIE AOT 26-12 dated June 06, 1994

The present revision 1 of this Airworthiness Directive replaces original issue.

EFFECTIVE DATES :

Original issue : 30 JULY 1994
Revision 1 : 08 OCTOBER 1994

n/C

September 28, 1994

AIRBUS INDUSTRIE
A300-600 ; A310 Aircraft

94-169-161(B) R1