

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 95-098-066(B)
In case of any difficulty, reference should be made to the French original issue.

AIRBUS INDUSTRIE

A320 Aircraft

Centre wing
Reinforcement of pressure of floor fittings

This Airworthiness Directive applies to AIRBUS INDUSTRIE A320 -111, -211 and -231 aircraft models MSN 005 to 008, 010 to 014, 016 to 042 included.

In order to prevent initiation and propagation of damage evidenced during the fatigue tests, the following measures are rendered mandatory on the effective date of this Airworthiness Directive :

- Before accumulation of 16000 flights, reinforce pressure floor fittings in accordance with instructions of AIRBUS INDUSTRIE Service Bulletin A320-57-1013.

No further action is required after accomplishment of either this Airworthiness Directive or AIRBUS INDUSTRIE Service Bulletin A320-57-1013.

Ref. : AIRBUS INDUSTRIE Service Bulletin A320-57-1013
(or any further approved revision)

EFFECTIVE DATE : JUNE 03, 1995