

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 97-269-103(B)
In case of any difficulty, reference should be made to the French original issue.

AIRBUS INDUSTRIE

A320, A321, A319 aircraft

Toilet rinse valve

Applicability :

AIRBUS INDUSTRIE A320, A321 and A319 all models and all serial numbers having toilets equipped with Monogram rinse valve PN 15800-348 rev. C and without AIRBUS INDUSTRIE modification 26145 or AIRBUS INDUSTRIE Service Bulletin A320-38-1049.

Reasons :

An incorrect functioning of the rinse valve Monogram PN 15800-348 Rev. C could cause an overflow of the toilet bowl. As consequence, during aircraft pitch down, a certain quantity of water coming from toilet(s) could fall down the avionic computers.

Actions :

Mandatory on the effective date of this Airworthiness Directive, unless already accomplished.

Before October 4, 1998, replace all Monogram rinse valves PN 15800-348 Rev. C installed on toilet(s) in accordance with AIRBUS INDUSTRIE Service Bulletin A320-38-1049.

References :

AIRBUS INDUSTRIE Service Bulletin A320-38-1049.

EFFECTIVE DATE : OCTOBER 04, 1997