# **AIRWORTHINESS DIRECTIVE**

## released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are madatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref.: 98-249-252(B)
In case of any difficulty, reference should be made to the French original issue.

#### **AIRBUS INDUSTRIE**

#### A300-600 Aircraft

Fuel system - Modification to the FLSA (Fuel Level Sensing System Amplifier) (ATA 28)

#### **APPLICABILITY**

AIRBUS INDUSTRIE A300-600 aircraft, all certified models and all serial numbers on which AIRBUS INDUSTRIE modification n° 4801 (aircraft fitted with the "Trim tank") has been embodied in production, except for aircraft on which modification n° 11683 (AIRBUS INDUSTRIE Service Bulletin A300-28-6055) has been embodied.

#### **REASON**

The trim tank overflow sensors are not supplied in flight on aircraft fitted with FLSA P/N 722-295-2; this, combined with a failure of the fuel level indicators, could cause continuous fuel transfer to the trim tank (with fuel loss in flight).

### **ACTION**

- At the effective date of this Airworthiness Directive, on all aircraft on which AIRBUS INDUSTRIE modification n° 10778 (AIRBUS INDUSTRIE Service Bulletin A300-31-6051) has already been embodied:
  - Replace the FLSAs in compliance with the instructions of AIRBUS INDUSTRIE Service Bulletin A300-28-6055 before August 31st, 1998.
- 2. After the effective date of this Airworthiness Directive, any aircraft modified in accordance with the instructions of AIRBUS INDUSTRIE Service Bulletin A300-31-6051 will have to be modified at the same in accordance with the instructions of AIRBUS INDUSTRIE Service Bulletin A300-28-6055.

REF.: AIRBUS INDUSTRIE Service Bulletin A300-28-6055 (original issue or any revision approved at a later date)
AIRBUS INDUSTRIE Service Bulletin A300-31-6051 (original issue or any revision approved at a later date).

July 01, 1998 AIRBUS INDUSTRIE 98-249-252(B)

GSAC	AIRWORTHINESS DIRECTIVE	ref.:	98-87R-252(B)	Page n° 2
EFFECTIVE DATE : JULY 11, 1998				
n/JYR				