

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 98-292-117(B)
In case of any difficulty, reference should be made to the French original issue.

AIRBUS INDUSTRIE

A321 Aircraft

Emergency escape slide (ATA 25)

APPLICABILITY

This Airworthiness Directive applies to AIRBUS INDUSTRIE A321 aircraft all certified models, all serial numbers without AIRBUS INDUSTRIE modification 27036 or without AIRBUS INDUSTRIE Service Bulletin A320-25-1199.

REASON

Loss of emergency escape slide in flight could lead to damage to the aircraft structure and on the overflow territories.

ACTION

Before August 31, 2001, modify the escape slide at doors 2 and 3 in accordance with instructions given in AIRBUS INDUSTRIE Service Bulletin A320-25-1199.

REF. : AIRBUS INDUSTRIE Service Bulletin A320-25-1199
(or any further approved revision)

EFFECTIVE DATE : AUGUST 08, 1998.

n/JYR

July 29, 1998

AIRBUS INDUSTRIE
A321 Aircraft

98-292-117(B)