



**Airworthiness
Directive
2001-304/2**

Luftfahrt-Bundesamt

Airworthiness Directive Section
Hermann-Blenk-Str. 26
38108 Braunschweig
Federal Republic of Germany

Eurocopter Deutschland

Effective Date: 19 October 2001

Affected:

Kind of aeronautical product:	Helicopter
Manufacturer:	Eurocopter Deutschland GmbH, Ottobrunn, Germany
Type:	EC 135
Models affected:	EC 135 T1
Serial numbers affected:	all which are equipped with Arrius 2B1 engines
German Type Certificate No.:	3061

Subject:

Engine, automatic engine control

Reason:

Installation of a new engine-control software and introduction of a detailed description of the starting procedure in order to sustain automatic engine control.

Action:

Software installation in accordance with the technical publication EC135-71A-019 or in accordance with EC135-71A-020 and incorporation of the preliminary change of the flight manual in accordance with the instructions laid out in the technical publication EC135-71A-021.

Additional actions in accordance with these mentioned technical publications.

Compliance:

Instructions on compliance in accordance with the technical publications of the manufacturer.

Technical publication of the manufacturer:

Eurocopter Deutschland EC135 Alert Service Bulletins No. EC135-71A-019, EC135-71A-020 Revision 01 and EC135-71A-021

These documents become herewith part of this AD and must be obtained from Messrs.:

Eurocopter Deutschland
P.O. Box
81663 München
Phone: + 49 (0) 89 6000-6060
Fax: + 49 (0) 89 6000-9137

Note:

This Airworthiness Directive supersedes the AD-No. 2001-304 dated October 18, 2001

Enquiries regarding this Airworthiness Directive should be referred to Mr. Martin Borsum, Airworthiness Directive Section, at the above address, fax-no. 0049 531/2355-720. Please note, that in case of any difficulty, reference should be made to the German issue!

LTA's / AD's and Technical Notes are published on the internet at <http://www.lba.de>