



AGÊNCIA NACIONAL DE AVIAÇÃO CIVIL – BRAZIL

BRAZILIAN AIRWORTHINESS DIRECTIVE

ERRATA

AD No.: 2016-04-02

Effective Date: 04 Apr. 2016

AD No. 2016-04-02 - EMBRAER - Amendment 39-1398.

This Errata is issued to correct a printing error in the original English version of this Airworthiness Directive.

On paragraph e) and g) of COMPLIANCE section, where it reads:

(e) The actions required by paragraph (d) of this AD may be done by inserting a copy of Embraer Operational Bulletin (OB) 500-001/16, original issue, dated March 12, 2016, or Embraer OB 505-001/16, original issue, dated March 12, 2016, as applicable, into the Limitations section of the AFM.

(...)

(g) You must use Embraer S.A. OB 500-001/16, original issue, dated March 12, 2016, or Embraer OB 505-001/16, original issue, dated March 12, 2016, as applicable, to do the actions required by this AD, unless the AD specifies otherwise.

.shall be read as:

(e) The actions required by paragraph (d) of this AD may be done by inserting a copy of Embraer Operational Bulletin (OB) 500-001/16, original issue, dated March 07, 2016, or Embraer OB 505-001/16, original issue, dated March 12, 2016, as applicable, into the Limitations section of the AFM.

(...)

(g) You must use Embraer S.A. OB 500-001/16, original issue, dated March 07, 2016, or Embraer OB 505-001/16, original issue, dated March 12, 2016, as applicable, to do the actions required by this AD, unless the AD specifies otherwise.

Please modify the original AD text and attach this Errata to it.

NOTE: Original in Portuguese language signed and available in the files of the Aeronautical Products Certification Branch (GGCP) of the National Civil Aviation Agency (ANAC).