

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 1978-205(A) R1
In case of any difficulty, reference should be made to the French original issue.

SOCATA

RALLYE 150, 180, MS 892, MS893 aeroplanes

Engine mount (ATA 71)

1. APPLICABILITY

The present Airworthiness Directive is applicable to SOCATA aeroplanes Rallye models 150T, 150ST and 180T and also MS 892 model A150 and MS 893 all models, equipped with an engine mount ref. 892.51.0.035.0.

Note 1: The engine mount ref. 892.51.0.035.0 may have been installed on new aeroplanes between April 1st, 1978 and November 6, 1978, or on previous aeroplanes by application of SOCATA "Information Bulletin" No. 39 and/or Airworthiness Directive No. 78-149(A).

Note 2: The present Revision 1 does not apply to aeroplanes on which the original edition of the present Airworthiness Directive has already been applied.

2. REASON

The original edition of the present Airworthiness Directive refers to the AD No. 78-149(A) which has been cancelled and replaced by the Airworthiness Directive No. 2001-400(A).

3. MANDATORY ACTIONS AND COMPLIANCE TIME

The following measures are made mandatory from the effective date of the present Revision 1 of this Airworthiness Directive:

Before next flight, replace the engine mount by an engine mount with another reference, approved on the concerned aeroplane.

Record the application of the present Revision 1 of this Airworthiness Directive in the aircraft log book.

This Revision 1 replaces original AD 78-205(A) dated November 06, 1978.

EFFECTIVES DATES :

Original AD : NOVEMBER 08, 1978
Revision 1 : SEPTEMBER 29, 2001

n/RH

September 19, 2001

SOCATA
RALLYE 150, 180, MS 892, MS 893 aeroplanes

1978-205(A) R1