



4000-3007-2022-0013262

AD ISR-I-53-19-10-5 R01

Date: 15.Nov.2022

AIRWORTHINESS DIRECTIVE

This Airworthiness Directive, issued by the Civil Aviation Authority in accordance with the Israeli Air Navigation Regulations applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

APPLIES TO: GALP model G280 aircraft serial numbers 2001 through 2184 certificated in any category.

SUBJECT: Fwd. Fuel Tank Probes Clearance Verification

REASON: During check of the Fwd. Fuel Tank it has been found that a possibility of an unaccepted clearance condition between fuel probes (probe no.1 and 3) and the fuel tank structure might exist.

Reason for

Revision 1 Update compliance time of initial issue of AD ISR-I-53-19-10-5

ACTION: Check and adjust clearance between fuel probes and forward fuel tank structure in accordance to Gulfstream Service Bulletin 280-53-287 dated Sep. 26, 2019 or later approved revision.

COMPLIANCE: Unless already accomplished, comply with this AD at the next suitable planned maintenance inspection not later than 30 December 2023.

EFFECTIVE DATE: Revision 1: November 30, 2022

Initial release: November 30, 2019.

FOR FURTHER INFORMATION CONTACT: Mr.Saul Pascal, Initial Airworthiness Engineering Branch, CAAI - P.O.Box 1101, 3 Golan Street, Airport City, Israel, 70151 Telephone: 972-3-9774583, Fax: 972-3-9774592, E-mail: pascals@mot.gov.il