



**AGÊNCIA NACIONAL DE AVIAÇÃO CIVIL - BRAZIL**

**BRAZILIAN AIRWORTHINESS DIRECTIVE**

**AD No.: 2022-05-03**

**Effective Date: 25 May 2022**

The following Brazilian Airworthiness Directive (AD), issued by the Agência Nacional de Aviação Civil (ANAC) in accordance with provisions of Chapter IV, Title III of Código Brasileiro de Aeronáutica - Law No. 7,565 dated 19 December 1986 - and Regulamento Brasileiro da Aviação Civil (RBAC) 39, applies to all aircraft registered in the Registro Aeronáutico Brasileiro. No person may operate an aircraft to which this AD applies, unless it has previously complied with the requirements established herein.

**AD No. 2022-05-03 - EMBRAER / 39-1495.**

**APPLICABILITY:**

This Airworthiness Directive (AD) applies to Embraer S.A. model ERJ 170 100 LR, ERJ 170 100 SE, ERJ 170 100 STD, ERJ 170 100 SU, ERJ 170 200 LR, ERJ 170 200 STD, ERJ 170 200 SU and ERJ 170 200 LL airplanes, all serial numbers, equipped with Honeywell Primus EPIC software versions up to 25.8, inclusive, or versions 27.1 through 27.3.

**CANCELLATION / REVISION:**

Not applicable.

**REASON:**

It was detected a case of uncommanded setting of the barometric reference in both primary flight displays (PFD) due to the architecture of data communication of the Control I/O modules, which interconnect the display controllers to the air data system. As there is a possibility of erroneous indications for both pilots combined with possible adverse meteorological conditions resulting in an increase of crew workload, which could interfere in decisions that shall be taken by the crew during critical phases of the flight, this is considered an unsafe condition.

Since this condition may occur in other airplanes of the same type and affects flight safety, a corrective action is required. Thus, sufficient reason exists to request compliance with this AD in the indicated time limit.

**REQUIRED ACTION:**

This AD requires the installation of newer versions of the Honeywell Primus EPIC software.

**COMPLIANCE:**

Required as indicated below, unless for aircraft which are already equipped with the

software versions required by this AD.

**(a) Software update**

(1) For airplanes equipped with Primus EPIC software versions 27.1 through 27.3, within 18 months after the effective date of this AD, install Primus EPIC software version 27.4 or higher. For the installation of version 27.4, use the Service Bulletin Embraer 170 31 0074 revision 02, or further revisions approved by ANAC. For higher versions of the software, use the applicable service bulletin as recommended by the manufacturer.

(2) For airplanes equipped with Primus EPIC software versions up to 25.8, inclusive, within 18 months after the effective date of this AD, install Primus EPIC software version 25.9 or higher, except versions 27.1. through 27.3. For the installation of version 25.9, use the Service Bulletin Embraer 170 31 0073 revision 01, or further revisions approved by ANAC. For higher versions of the software, use the applicable service bulletin as recommended by the manufacturer.

**NOTE 1:** The utilization of versions 27.1 through 27.3 and versions up to 25.8, inclusive, of the Primus EPIC software is being discontinued from the date of accomplishment of this AD.

**NOTE 2:** This AD requires the installation of software versions which are more up-to-date than the versions required by ANAC AD 2019 10 02, therefore the accomplishment of this AD also covers the accomplishment of ANAC AD 2019 10 02.

**(b) Credit for previous actions**

This paragraph provides credit for the actions specified in paragraph (a) of this AD if those actions were performed before the effective date of this AD according to the original revision, dated May 19th 2021, or revision 01, dated August 04th 2021, of the Service Bulletin Embraer 170 31 0074; or according to the original revision, dated June 11th 2021, of the Service Bulletin Embraer 170 31 0073.

**(c) Alternative Methods of Compliance (AMOC)**

(1) A different method or a different compliance time, with the requirements of this AD, may be used if approved by the Manager of the Continuing Airworthiness Technical Branch (GTAC) of ANAC.

(2) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (c)(2)(i) and (c)(2)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under a RC step and any figures identified in a RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

**(d) Material incorporated by reference**

You must use the following service information for the installation of the Primus EPIC software versions 25.9 and 27.4 as required by this AD:

(1) Service Bulletin Embraer 170 31 0074, revision 02, dated September 29<sup>th</sup>, 2021.

(2) Service Bulletin Embraer 170 31 0073, revision 01, dated December 16<sup>th</sup>, 2021.

Record compliance with this AD in the applicable maintenance log book.

**CONTACT:**

For additional technical information, contact:

National Civil Aviation Agency (ANAC)  
Continuing Airworthiness Technical Branch (GTAC)  
Rua Doutor Orlando Feirabend Filho, nº 230  
Centro Empresarial Aquáriu - Torre B - 14º ao 18º andares  
Parque Residencial Aquáriu  
CEP 12246-190 – São José dos Campos - SP, BRAZIL.  
Tel: (12) 3203-6600; E-mail: pac@anac.gov.br

**APPROVAL:**

ROBERTO JOSÉ SILVEIRA HONORATO  
Head of Department  
Department of Airworthiness  
ANAC

**NOTE:** Original in Portuguese language signed and available in the files of the Continuing Airworthiness Technical Branch (GTAC) of the National Civil Aviation Agency (ANAC).

---

**Referência:** Processo nº 00066.002779/2022-57

SEI nº 7133951