



No.	CF-2006-23R1	1/1
Issue Date	12 March 2007	

AIRWORTHINESS DIRECTIVE

The following airworthiness directive (AD) may be applicable to an aircraft which our records indicate is registered in your name. ADs are issued pursuant to *Canadian Aviation Regulation (CAR) 593*. Pursuant to **CAR 605.84** and the further details of **CAR Standard 625, Appendix H**, the continuing airworthiness of a Canadian registered aircraft is contingent upon compliance with all applicable ADs. Failure to comply with the requirements of an AD may invalidate the flight authorization of the aircraft. Alternative means of compliance shall be applied for in accordance with **CAR 605.84** and the above-referenced **Standard**.

This AD has been issued by the Continuing Airworthiness Division (AARDG), Aircraft Certification Branch, Transport Canada, Ottawa, telephone 613 952-4357.

Number: CF-2006-23R1

Subject: Main Rotor Latch Bolts - Removal from Service

Effective: 19 April 2007

Revision Supersedes Airworthiness Directive CF-2006-23 issued on 6 November 2006.

Applicability: Bell Helicopter Textron Canada (BHTC). Models 206 A and 206 B helicopters, up to serial number 3216 (inclusive), having main rotor latch bolts, part numbers 206-010-169-001/-003 and 206-011-122-003.

Compliance: As indicated.

Background: Reevaluation of the structural analysis indicates the need for the removal from service of bolts in this application.

Many Model 206A helicopters were converted into Model 206B. This revision clarifies applicability for those Model 206B helicopters that have serial numbers within the range of Model 206A.

Corrective Action: At the next scheduled main rotor hub disassembly, but no later than 18 May 2007, remove from service the applicable main rotor latch bolts and replace with airworthy parts as per Alert Service Bulletin (ASB) 206-06-109 dated 25 July 2006, or later revisions approved by Chief, Continuing Airworthiness Transport Canada.

Main rotor latch bolts listed in above applicability section held in stores are not to be installed.

Authorization: Minister of Transport, Infrastructure and Communities

Philip Tang
Acting Chief, Continuing Airworthiness

Contact: Mr. Bogdan Gajewski, Continuing Airworthiness, Ottawa, telephone 613-952-4450, facsimile 613-996-9178 or e-mail gajewsb@tc.gc.ca or any Transport Canada Centre.

Pursuant to **CAR 202.51** the registered owner of a Canadian aircraft shall, within seven days, notify the Minister in writing of any change of his or her name or address.

To request a change of address, contact the **Civil Aviation Communications Centre (AARC)** at **Place de Ville, Ottawa, Ontario K1A 0N8**, or **1-800-305-2059**, or www.tc.gc.ca/civilaviation/communications/centre/address.asp