



Incorporation of Bombardier ModSum 4-113723, which removes the parking brake hand pump lever from the RH side nacelle and re-installs the parking brake hand pump lever in the RH side equipment bay, also satisfies the requirements of this AD. Bombardier SBs 84-32-99, Initial Issue and Revision A, dated 26 January 2012 and 2 October 2012 respectively, or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada, provide approved instructions for incorporating ModSum 4-113723.

**Authorization:** For the Minister of Transport,

*ORIGINAL SIGNED BY*

Derek Ferguson  
Chief, Continuing Airworthiness

**Contact:** Robert Farinas, Continuing Airworthiness, Ottawa, telephone 613-952-4357, facsimile 613-996-9178 or e-mail [AD-CN@tc.gc.ca](mailto:AD-CN@tc.gc.ca) or any Transport Canada Centre.