



Accomplishment in accordance with previous revisions of Bombardier SB 8-24-84 also meets the requirements of Part II of this AD.

**Part III - Applicable to aeroplanes with Phoenix DC GCU Part Number GC-1010-24-5DIV or GC-1010-24-5DV Installed**

Replace the DC GCU Label in accordance with Section 3.B, Part 2 of the Accomplishment Instructions in Bombardier SB 8-24-84, Revision D, dated 10 April 2014, or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada.

**Authorization:** For the Minister of Transport,

*ORIGINAL SIGNED BY*

Derek Ferguson  
Chief, Continuing Airworthiness

**Contact:** Helen Tsai, Continuing Airworthiness, Ottawa, telephone 613-952-4357, facsimile 613-996-9178 or e-mail [AD-CN@tc.gc.ca](mailto:AD-CN@tc.gc.ca) or any Transport Canada Centre.