

Datum der Bekanntgabe: 21.11.1996

Muster: Dornier
Dornier 328

AD der ausländischen Behörde:
-keine-

Geräte-Nr.:
2534

Technische Mitteilungen des Herstellers:
Dornier 328 Service Bulletin No. 328-29-194 vom 17.10.1996

Betroffenes Luftfahrtgerät:

Dornier
Dornier 328-100
- Werk-Nrn.: 3064 und 3065

Betrifft:

Hydraulikanlage, Hydraulikleitung ("roll spoiler tube") P/N 001A291A6060

Maßnahmen:

Austausch der Hydraulikleitung "roll spoiler tube"

Fristen:

Durchführung bis spätestens 30.11.1996.

Durch die vorgenannten Mängel ist die Lufttüchtigkeit des Luftfahrtgerätes derart beeinträchtigt, das es nach Ablauf der genannten Fristen nur in Betrieb genommen werden darf, wenn die angeordneten Maßnahmen ordnungsgemäß durchgeführt worden sind. Im Interesse der Sicherheit des Luftverkehrs, das in diesem Fall das Interesse des Adressaten am Aufschub der angeordneten Maßnahmen überwiegt, ist es erforderlich die sofortige Vollziehung dieser LTA anzuordnen.

Rechtsbehelfsbelehrung:

Gegen diese Verfügung kann innerhalb eines Monats nach Bekanntgabe Widerspruch eingelegt werden. Der Widerspruch ist schriftlich oder zur Niederschrift beim Luftfahrt-Bundesamt, Lilienthalplatz 6, 38108 Braunschweig einzulegen.



Luftfahrt-Bundesamt
-AD-Department-

Airworthiness Directive

*In case of any difficulty, reference should be made
to the German original issue*

96-323 Dornier

Effective Date: November 21, 1996

Affected airplanes:

German Type Certificate No.: 2534

Dornier 328-100

- S/No's.: 3064 and 3065

Subject:

Hydraulic Power - Exchange of roll spoiler tube.

Reason:

Possible manufacturing failure of roll spoiler tube assy.

Action:

Exchange roll spoiler tube assy.

Compliance:

Exchange must be performed not later than November 30, 1996.

Technical publication of the manufacturer:

Dornier 328 Service Bulletin No. 328-29-194, dated October 17, 1996 becomes herewith part of this AD and may be obtained from Messrs.

Faichild / Dornier
P.O. Box 1103

D-82230 Wessling
Federal Republic of Germany

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the log by a licensed inspector.

* * *