

Datum der Bekanntgabe: 13.03.1997

Muster: Dornier
Dornier 328

AD der ausländischen Behörde:
- keine -

Geräte-Nr.:
2534

Technische Mitteilungen des Herstellers:
Dornier 328 Alert Service Bulletin Nr. 328-30-013 Revision 1
vom
21.02.1997.

Betroffenes Luftfahrtgerät:

Dornier
Dornier 328

- **Baureihen:** Dornier 328-100

- **Werk-Nrn.:** alle

Betrifft:

Vereisungs- und Regenschutzanlage, Luftschraubenenteisung - evtl. Ausfall der Enteisungsanlage der Propeller ohne Erschei nen einer Warnmeldung auf dem 'EICAS'

Maßnahmen:

Inspektion der Luftschrauben-Enteisungsanlage.

Fristen:

Durchführung bis zum 15.03.1997.

Durch die vorgenannten Mängel ist die Lufttüchtigkeit des Luftfahrtgerätes derart beeinträchtigt, daß es nach Ablauf der genannten Fristen nur in Betrieb genommen werden darf, wenn die angeordneten Maßnahmen ordnungsgemäß durchgeführt worden sind. Im Interesse der Sicherheit des Luftverkehrs, das in diesem Fall das Interesse des Adressaten am Aufschub der angeordneten Maßnahmen überwiegt, ist es erforderlich die sofortige Vollziehung dieser LTA anzuordnen.

Rechtsbehelfsbelehrung:

Gegen diese Verfügung kann innerhalb eines Monats nach Bekanntgabe Widerspruch eingelegt werden. Der Widerspruch ist schriftlich oder zur Niederschrift beim Lufthfahrt-Bundesamt, Lilienthalplatz 6, 38108 Braunschweig einzulegen.

* * *



**Airworthiness
Directive
97-066**

Luftfahrt-Bundesamt
Airworthiness Directive Section
Lilienthalplatz 6
38108 Braunschweig
Federal Republic of Germany

Dornier

Effective Date: March 13, 1997

Affected:

Kind of aeronautical product:	Aircraft
Manufacturer:	Dornier, Wessling, Germany
Type:	Dornier 328
Models affected:	Dornier 328-100
Serial numbers affected:	all
German Type Certificate No.:	2534

Subject:

Ice & Rain Protection
- Inspection of Propeller De-ice system

Reason:

Possibility of Propeller De-ice system failure without an indication on the EICAS.

Action:

One time inspection of Propeller De-ice system.

Compliance:

Action must be performed not later than March 15, 1997.

Technical publication of the manufacturer:

Dornier 328 Alert Service Bulletin No. 328-30-013 Revision 1 dated February 21, 1997 which becomes herewith part of this AD and must be obtained from Messrs.:

Fairchild /Dornier
P.O. Box 11 03

D-82230 Wessling
Federal Republik of Germany

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the log book by a licensed inspector.