
Issued by the Civil Aviation Authority of New Zealand in accordance with section 72I(3A) of the Civil Aviation Act. An Airworthiness Directive (AD) contains regulatory information which is mandatory. An operator of an aircraft must not operate the aircraft unless the operator complies with every applicable AD issued by the Director in accordance with section 72I(3A) of the Civil Aviation Act. An AD is issued where the Director believes on reasonable grounds that an unsafe condition exists in an aircraft or aeronautical product.

DCA/750XL/22A Ventilation Hose behind Instrument Panel - Inspection

- Applicability:** Pacific Aerospace 750XL aircraft, all S/N up to and including 220.
- Requirement:** To prevent chafing damage on components and wiring behind the instrument panel caused by the ventilation SCAT hose, accomplish the following:
1. Accomplish the requirements in the Accomplishment Instructions 2.A of Pacific Aerospace Mandatory Service Bulletin (MSB) PACSB/XL/083 issue 2, dated 16 January 2018, or later approved revision.
- If any signs of chafing or damage is found, accomplish an approved repair before further flight.
2. Accomplish the requirements in the Accomplishment Instructions 2.B of MSB PACSB/XL/083.
- Compliance:**
1. Before further flight after 28 December 2017 (the effective date of DCA/750XL/22).
 2. At the next scheduled maintenance inspection, or by 31 March 2018, whichever is the later, unless previously accomplished.
- Effective Date:** DCA/750XL/22 - 28 December 2017
DCA/750XL/22A - 28 February 2018
- Background:** This AD is prompted by two reports of finding abrasion damage behind the instrument panel caused by ventilation hose chafing. This AD supersedes DCA/750XL/22 to introduce Pacific Aerospace Limited Mandatory Service Bulletin (MSB) PACSB/XL/083 issue 2, dated 16 January 2018. There are no changes to the AD applicability. The PAL MSB revised to include an optional scat hose configuration which may be found fitted to certain aircraft, to clarify that the self-adhesive mounts should be attached directly to the metallic surface, and recommend that 25mm wide 3M Scotch 27 glass cloth tape is used to wrap the scat hose.