



C
(TYPICAL)

 AREA TO BE INSPECTED

IDT_RRJ_NDT_55_10_00_003_002_A02_E

Inspection of the Horizontal Stabilizer Rear Spar Web in the Area of the Cut-Outs Between Ribs 0-1 and 1-2
Figure 401 (Sheet 2 of 2)