

Ref. Publications:

M&D Flugzeugbau GmbH MSB 808-18 Revision 04 dated 10 October 2018.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. Based on the required actions and the compliance time, EASA have decided to issue a Final AD with Request for Comments, postponing the public consultation process until after publication.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#).
5. For any question concerning the technical content of the requirements in this AD, please contact: M&D Flugzeugbau GmbH & Co.KG, Stecker Str. 1, D-26446 Friedeburg, Germany, Tel: +49 4465 97878 0, Fax: +49 4465 97878 99, Webpage: www.md-flugzeugbau.de, E-mail: info@md-flugzeugbau.de.

Superseded

