



Airworthiness Directive

AD No.: 2018-0285

Issued: 20 December 2018

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

PILATUS AIRCRAFT Ltd.

Type/Model designation(s):

PC-6 aeroplanes

Effective Date: 03 January 2019

TCDS Number(s): Switzerland No. F 56-10

Foreign AD: Not applicable

Supersedure: This AD supersedes EASA AD 2014-0181 dated 31 July 2014.

ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitations Section – Amendment

Manufacturer(s):

Pilatus Aircraft Ltd. and Fairchild Republic Company, formerly Fairchild Industries, Fairchild Heli Porter and Fairchild-Hiller Corporation

Applicability:

PC-6 aeroplanes, all models, all manufacturer serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

The ALS: Pilatus PC-6 Aircraft Maintenance Manual (AMM) Chapter 04-00-00 Document Number 01975, or Chapter 04-00-00 Document Number 01975 (IAC AR), both issue 27, and Airworthiness Limitations Document (ALS) Document Number 02334, issue 8, all dated 21 November 2018, as applicable to aeroplane model.

The AMP: The approved aircraft maintenance programme (AMP) on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane.

New and/or more restrictive tasks and limitations: This includes all maintenance tasks and airworthiness limitations that are new and all tasks for which a threshold, value or interval was



reduced, which were introduced into the ALS (as defined in this AD) since the previous ALS Revision that is currently incorporated in the AMP.

Reason:

The airworthiness limitations and certification maintenance instructions for Pilatus PC-6 aeroplanes, which are approved by EASA, are currently defined and published in Pilatus PC-6 AMM Chapter 4, and in the ALS, depending on aeroplane model. These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.

Previously, EASA issued AD 2014-0181 to require implementation of the maintenance tasks and airworthiness limitations as specified in Pilatus PC-6 AMM Document Number 01975 at issue 19 and ALS Document Number 02334 at issue 4, as applicable.

Since that AD was issued, Pilatus issued the ALS, as defined in this AD, which introduces new and/or more restrictive tasks and limitations.

For the reason described above, this AD retains the requirements of EASA AD 2014-0181, which is superseded, and requires accomplishment of the actions specified in the ALS.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Maintenance Tasks and Replacement of Life Limited Parts:

- (1) From the effective date of this AD, accomplish the following actions, as specified in the ALS, as applicable to aeroplane model and depending on aeroplane configuration:
 - (1.1) Replace each component before exceeding the applicable life limit, and
 - (1.2) Within the thresholds and intervals (see Note 1 of this AD), accomplish all applicable maintenance tasks.

Note 1: For the purpose of this AD, the thresholds and intervals as defined in the 'Compliance Time' pages of the ALS include specific compliance times for certain tasks. Where certain parts have reached or exceeded a threshold, the specified allowed additional replacement time for these parts can be counted from the effective date of this AD.

Corrective Action(s):

- (2) In case of finding discrepancies (as defined in the ALS) during accomplishment of any task as required by paragraph (1) of this AD, within the compliance time specified in the ALS, accomplish the applicable corrective action(s) in accordance with applicable Pilatus maintenance documentation. If no compliance time is identified in the ALS, accomplish the applicable corrective action(s) before next flight. If a detected discrepancy is not identified in the ALS, before next flight, contact Pilatus for approved instructions and accomplish those instructions accordingly.



AMP Revision:

- (3) Within 12 months after the effective date of this AD, revise the approved AMP by incorporating the limitations, tasks and associated thresholds and intervals described in the ALS, as applicable to aeroplane model and depending on aeroplane configuration.

Credit:

- (4) If, before the effective date of this AD, the AMP has been revised to incorporate the maintenance tasks and life limitations as specified in a previous ALS revision, that action ensures the continued accomplishment of those tasks and limitations.

Consequently, for an aeroplane to which that AMP applies, it is acceptable to accomplish the new and/or more restrictive tasks and limitations as specified in the ALS, as applicable to aeroplane model and depending on aeroplane configuration, within the compliance times (see Note 1 of this AD) as specified in the ALS, to comply with paragraph (1) of this AD.

For that AMP, it is acceptable to incorporate the new and/or more restrictive tasks and limitations as specified in the ALS, as applicable to aeroplane model and depending on aeroplane configuration, as specified in the ALS, into the AMP to comply with paragraph (3) of this AD.

Recording AD compliance:

- (5) When the AMP of an aeroplane has been revised as required by paragraph (3) or (4) of this AD, as applicable, that action ensures continued accomplishment of the tasks as required by paragraphs (1) and (2) of this AD for that aeroplane. Consequently, after revising the AMP, as required by paragraph (3) or (4) of this AD, as applicable, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

Ref. Publications:

Pilatus PC-6 ALS Document Number 02334, issue 8 dated 21 November 2018.

Pilatus PC-6 AMM, Chapter 04-00-00, Document Number 01975, issue 27 dated 21 November 2018.

Pilatus PC-6 AMM, Chapter 04-00-00, Document Number 01975 (IAC AR), issue 27 dated 21 November 2018 (approved by EASA on behalf of the Interstate Aviation Committee for aeroplanes registered in the Commonwealth of Independent States).

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. Based on the required actions and the compliance time, EASA have decided to issue a Final AD with Request for Comments, postponing the public consultation process until after publication.



3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#).
5. For any question concerning the technical content of the requirements in this AD, please contact: Pilatus Aircraft Ltd, Customer Support Manager, CH-6371 Stans, Switzerland
Telephone: +41 41 619 33 33, Fax: +41 41 619 73 11
E-mail: SupportPC12@pilatus-aircraft.com; Website: www.pilatus-aircraft.com.

SUPERSEDED

