

## Airworthiness Directive

**AD No.:** 2019-0050

**Issued:** 11 March 2019

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

### Design Approval Holder's Name:

AIRBUS

### Type/Model designation(s):

A340 aeroplanes

**Effective Date:** 25 March 2019

**TCDS Number(s):** EASA.A.015

**Foreign AD:** Not applicable

**Supersedure:** None

## ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitations Section Part 3 – Certification Maintenance Requirements – Amendment

### Manufacturer(s):

Airbus, formerly Airbus Industrie

### Applicability:

Airbus A340-211, A340-212, A340-213, A340-311, A340-312, A340-313, A340-541, A340-542, A340-642 and A340-643 aeroplanes, all manufacturer serial numbers (MSN).

### Definitions:

For the purpose of this AD, the following definitions apply:

**The ALS:** Airbus A340 Airworthiness Limitations Section (ALS) Part 3, Revision 04.

**The AMP:** The approved Aircraft Maintenance Programme (AMP) on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane. For aeroplanes registered in Europe, complying with the approved AMP is required by Commission Regulation (EU) [1321/2014](#), Part M.A.301, paragraph 3.

**New and/or more restrictive tasks:** This includes all tasks that are new and all tasks for which a threshold or interval was reduced, which were introduced into the ALS (as defined in this AD) since the previous ALS Revision that is currently incorporated in the AMP.

**Reason:**

The airworthiness limitations for the Airbus A340 aeroplanes, which are approved by EASA, are currently defined and published in the A340 ALS documents. The airworthiness limitations applicable to the Certification Maintenance Requirements (CMR), which are approved by EASA, are published in the ALS.

Failure to accomplish these instructions could result in an unsafe condition.

Previously, EASA issued AD 2016-0066 to require accomplishment of all maintenance tasks as described in A340 ALS Part 3 at Revision 03.

Since that AD was issued, Airbus published the ALS, including new and/or more restrictive requirements.

For the reasons described above, this AD takes over the requirements for Airbus A340 aeroplanes from EASA AD 2016-0066 and requires accomplishment of the actions specified in the ALS.

**Required Action(s) and Compliance Time(s):**

Required as indicated, unless accomplished previously:

**Maintenance Tasks:**

- (1) From the effective date of this AD, within the thresholds and intervals as specified in the ALS (see Note 1 of this AD), accomplish all tasks as specified in the ALS, as applicable to aeroplane model and depending on aeroplane configuration.

Note 1: For the purpose of this AD, the thresholds and intervals as defined in the 'Compliance Time' pages of the ALS include specific compliance times for certain tasks.

**Corrective Action(s):**

- (2) In case of finding discrepancies during accomplishment of any task as required by paragraph (1) of this AD, before next flight, accomplish the applicable corrective action(s) in accordance with the applicable Airbus maintenance documentation. If a detected discrepancy cannot be corrected by using existing Airbus instructions, before next flight, contact Airbus for approved instructions and accomplish those instructions accordingly.

**AMP Revision:**

- (3) Within 12 months after the effective date of this AD, revise the approved AMP by incorporating the maintenance tasks and associated thresholds and intervals described in the ALS, as applicable to aeroplane model and depending on aeroplane configuration.

**Credit:**

- (4) If, before the effective date of this AD, the AMP has been revised to incorporate the tasks as specified in A340 ALS Part 3 at Revision 03, that action ensures the continued accomplishment of those tasks.



Consequently, for an aeroplane to which that AMP applies, it is acceptable to accomplish the new and/or more restrictive tasks as specified in the ALS, as applicable to aeroplane model and depending on aeroplane configuration, within the compliance times (see Note 1 of this AD) as specified in the ALS, to comply with paragraph (1) of this AD.

For that AMP, it is acceptable to incorporate the new and/or more restrictive tasks, as applicable to aeroplane model and depending on aeroplane configuration, as specified in the ALS, into the AMP to comply with paragraph (3) of this AD.

#### Recording AD compliance:

- (5) When the AMP of an aeroplane has been revised as required by paragraph (3) or (4) of this AD, as applicable, that action ensures continued accomplishment of the tasks as required by paragraphs (1) and (2) of this AD for that aeroplane. Consequently, after revising the AMP, as required by paragraph (3) or (4) of this AD, as applicable, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

#### Ref. Publications:

Airbus A340 ALS Part 3 Revision 04 dated 15 October 2018.

The use of later approved revisions and variations of the above-mentioned document is acceptable for compliance with the requirements of this AD.

#### Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 17 December 2018 as PAD 18-180 for consultation until 14 January 2019. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#).
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – EIAL (Airworthiness Office), E-mail: [airworthiness.A330-A340@airbus.com](mailto:airworthiness.A330-A340@airbus.com).

