



## Airworthiness Directive Cancellation Notice

**AD No.:** 2024-0109-CN

**Issued:** 06 June 2024

Note: This Airworthiness Directive (AD) Cancellation Notice (CN) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

**Design Approval Holder's Name:**

LEONARDO S.p.A.

**Type/Model designation(s):**

AB206 helicopters

**Effective Date:** 06 June 2024

**TCDS Number(s):** EASA.R.140

**Foreign AD:** Not applicable

**Cancellation:** This Notice cancels Registro Aeronautico Italiano AD 69-20 Revision (Rev.) 1 dated 20 February 1969.

### ATA 67 – CANCELLED: Flight Controls – Tail Rotor Control Tube – Inspection / Replacement

---

**Manufacturer(s):**

Agusta S.p.A., formerly Costruzioni Aeronautiche Giovanni Agusta S.p.A.

**Applicability:**

AB206A helicopters, all serial numbers.

**Reason:**

Occurrences of wear beyond acceptable limits have been reported on the tail rotor control tube assembly, Part Number 206-001-021-9, where the tube contacts supporting fairleads.

This condition, if not detected and corrected, could lead to the rupture of the control tube and loss of control of the tail rotor.

To address this potential unsafe condition, ENAC Italy [at that time, Registro Aeronautico Italiano (RAI)] issued AD 69-20, later revised, to require repetitive inspections for wear at points, where the control tube contacts the fairleads through the tailboom.

Since that AD was issued, the required actions have been incorporated in the AB206A/B-SERIES-MPM Scheduled Maintenance Check 5-18. Furthermore, no further in-service events have been recorded. Therefore, the unsafe condition addressed by RAI AD 69-20 Rev. 1 does not exist anymore.



For the reasons described above, this Notice cancels RAI AD 69-20 Rev. 1.

**Required Action(s) and Compliance Time(s):**

None.

**Ref. Publications:**

Bollettino Tecnico BT206-25 Rev. A dated 11 February 1969.

**Remarks:**

1. This AD-CN was posted on 07 May 2024 as PAD 24-049-CN for consultation until 04 June 2024. No comments were received during the consultation period.
2. Enquiries regarding this AD-CN should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
3. For any question concerning the technical content of this AD-CN, please contact: Leonardo S.p.A. Helicopters, Customer Support & Services, Product Support Engineering & Licenses DPT, Via Giovanni Agusta 520, 21017 Cascina Costa di Samarate (VA) – Italy, Tel.: +39 0331 711429, Fax: +39 0331 915145, E-mail: [absereng.AW@leonardo.com](mailto:absereng.AW@leonardo.com).

