



Airworthiness Directive

AD No.: 2024-0121

Issued: 27 June 2024

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

ATR-GIE AVIONS de TRANSPORT RÉGIONAL

Type/Model designation(s):

ATR 42 aeroplanes

Effective Date: 11 July 2024

TCDS Number(s): EASA.A.084

Foreign AD: Not applicable

Supersedure: This AD supersedes EASA AD 2022-0199 dated 26 September 2022.

ATA 05 – Time Limits / Maintenance Checks – Certification Maintenance Requirements and Airworthiness Limitations – Amendment

Manufacturer(s):

ATR-GIE Avions de Transport Régional, formerly EADS ATR - Alenia, Aerospatiale Matra ATR - ALENIA, Aerospatiale - Alenia, Aerospatiale - Aeritalia

Applicability:

ATR 42-200, ATR 42-300 and ATR 42-320 aeroplanes, all manufacturer serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

The TLD: ATR 42-200/-300/-320 Time Limits Document (TLD) Revision 13.

The AMP: The Aircraft Maintenance Programme (AMP) contains the tasks on the basis of which the scheduled maintenance is conducted to ensure the continuing airworthiness of each operated aircraft. For aircraft operated under EU regulations, the operator or the owner ensures compliance with the AMP as stipulated in Commission Regulation (EU) [1321/2014](#).

New and/or more restrictive tasks and limitations: This includes all tasks and limitations that are new or for which a threshold and/or interval was reduced, which were introduced into the TLD, as defined in this AD, since the previous TLD Revision that is currently incorporated in the AMP.



Reason:

The airworthiness limitations and certification maintenance requirements for ATR 42-200, ATR 42-300 and ATR 42-320 aeroplanes, which are approved by EASA, are currently defined and published in the TLD. These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.

EASA previously issued AD 2022-0199 to require accomplishment of the actions as described in ATR 42-200/-300/-320 TLD Revision 12.

Since that AD was issued, ATR published the TLD, which contains new and/or more restrictive tasks and limitations.

For the reasons described above, this AD retains the requirements of EASA AD 2022-0199, which is superseded, and requires accomplishment of the actions specified in the TLD.

Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the action(s) required by this AD have been already accomplished:

Maintenance Tasks and Replacement of Life Limited Parts:

- (1) From the effective date of this AD, accomplish the following actions, as specified in the TLD, as applicable to aeroplane model and depending on aeroplane configuration:
 - (1.1) Replace each component before exceeding the applicable life limit, and
 - (1.2) Within the thresholds and intervals (see Note 1 of this AD), accomplish all applicable maintenance tasks.

Note 1: For the purpose of this AD, a specific one-time exceedance allowance (grace period) is defined for certain tasks in the 'Reason for revision' section of the TLD.

Corrective Action(s):

- (2) In case of finding discrepancies during accomplishment of any task as required by paragraph (1) of this AD, before next flight, accomplish the applicable corrective action(s) in accordance with the applicable ATR maintenance documentation. If a detected discrepancy cannot be corrected by using existing ATR instructions, before next flight, contact ATR for approved instructions and accomplish those instructions accordingly.

AMP Revision:

- (3) Within 12 months after the effective date of this AD, revise the approved AMP by incorporating the limitations, tasks and associated thresholds and intervals described in the TLD, as applicable to aircraft model and depending on aircraft configuration.



Credit:

- (4) If, before the effective date of this AD, the AMP has been revised to incorporate the maintenance tasks and life limitations as specified in ATR 42-200/-300/-320 TLD Revision 12, that action ensures the continued accomplishment of those tasks and limitations.

Consequently, for an aircraft to which that AMP applies, it is acceptable to accomplish the new and/or more restrictive tasks and limitations as defined in this AD, as applicable to aircraft model and depending on aircraft configuration, within the compliance times (see Note 1 of this AD) as specified in the TLD, to comply with paragraph (1) of this AD.

For that AMP, it is acceptable to incorporate the new and/or more restrictive tasks and limitations as specified in the TLD, as applicable to aircraft model and depending on aircraft configuration, into the AMP to comply with paragraph (3) of this AD.

Recording AD Compliance:

- (5) When the AMP of an aircraft has been revised as required by paragraph (3) or (4) of this AD, as applicable, that action ensures continued accomplishment of the tasks and limitations as required by paragraphs (1) and (2) of this AD for that aircraft. Consequently, after revising the AMP, as required by paragraph (3) or (4) of this AD, as applicable, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

Ref. Publications:

ATR 42-200/-300/-320 TLD Revision 13 dated 31 January 2024.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 23 May 2024 as PAD 24-058 for consultation until 20 June 2024. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.



5. For any question concerning the technical content of the requirements in this AD, please contact: ATR - GIE Avions de Transport Régional, Continued Airworthiness Service, Telephone: +33 (0)5 62 21 62 21, Fax: +33 (0) 5 62 21 67 18; E-mail: continued.airworthiness@atr-aircraft.com.

