



Notification of a Proposal to issue an Airworthiness Directive

PAD No.: 17-075

Issued: 14 June 2017

Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

Design Approval Holder's Name:

AIRBUS

Type/Model designation(s):

A318, A319, A320 and A321 aeroplanes

Effective Date: [TBD - standard: 14 days after AD issue date]

TCDS Number(s): EASA.A.064

Foreign AD: Not applicable

Supersedure: This AD supersedes EASA AD 2016-0092 dated 13 May 2016.

ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitations Section – Part 3 – Certification Maintenance Requirements - Amendment

Manufacturer(s):

Airbus (formerly Airbus Industrie)

Applicability:

Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A320-251N, A320-271N, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-271N, A321-231 and A321-232 aeroplanes, all manufacturer serial numbers.

Reason:

The airworthiness limitations for Airbus A320 family aeroplanes are currently defined and published in Airbus A318/A319/A320/A321 Airworthiness Limitations Section (ALS) documents. The airworthiness limitations applicable to the Certification Maintenance Requirements (CMR), which are approved by EASA, are published in ALS Part 3.



The instructions contained in the ALS Part 3 have been identified as mandatory actions for continued airworthiness. Failure to comply with these instructions could result in an unsafe condition.

Previously, EASA issued AD 2016-0092 to require accomplishment of all maintenance tasks as described in ALS Part 3 at Revision 03. The new ALS Part 3 Revision 05 (hereafter referred to as 'the ALS' in this AD) includes new and/or more restrictive requirements.

For the reason described above, this AD retains the requirements of EASA AD 2016-0092, which is superseded, and requires accomplishment of all maintenance tasks as described in the ALS.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Maintenance Tasks:

- (1) From the effective date of this AD, at intervals as defined in the ALS (see Note 1 of this AD), accomplish all maintenance tasks, as applicable to aeroplane model and depending on aeroplane configuration, as specified in the ALS.

Note 1: For the purpose of this AD, the intervals as defined in the 'Compliance Time' pages of the ALS include specific compliance times (grace periods) for certain tasks.

Corrective Action(s):

- (2) In case of finding discrepancies during accomplishment of any task as required by paragraph (1) of this AD, before next flight, accomplish the applicable corrective action(s) in accordance with the applicable Airbus maintenance documentation. If a detected discrepancy cannot be corrected by using existing Airbus instructions, before next flight, contact Airbus for approved instructions and accomplish those instructions accordingly.

Aircraft Maintenance Programme (AMP) Revision:

- (3) Within 12 months after the effective date of this AD, revise the approved AMP, on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane, by incorporating the maintenance tasks and associated intervals described in the ALS, as applicable to aeroplane model and depending on the aeroplane configuration.

Credit:

- (4) For an AMP that, on the effective date of this AD, is already updated to incorporate the maintenance tasks as specified in ALS Part 3 at Revision 03, or Revision 04, that action ensures (see Note 2 of this AD) the continued accomplishment of those tasks.

Consequently, for an aeroplane to which that AMP applies, it is acceptable to accomplish the new and more restrictive tasks, as applicable to aeroplane model and depending on aeroplane configuration, as defined in, and within the compliance times (see Note 1 of this AD) as specified in, the ALS, to comply with paragraph (1) of this AD.



For that AMP, it is acceptable to incorporate the new and more restrictive tasks, as applicable to aeroplane model and depending on aeroplane configuration, as defined in the ALS, into the AMP to comply with paragraph (3) of this AD.

Recording AD compliance:

- (5) When the AMP of an aeroplane has been revised as required by paragraph (3) or (4) of this AD, as applicable, that action ensures (see Note 2 of this AD) continued accomplishment of the tasks as required by paragraphs (1) and (2) of this AD for that aeroplane. Consequently, after revising the AMP, as required by paragraph (3) or (4) of this AD, as applicable, it is not necessary that accomplishment of individual tasks is recorded for demonstration of AD compliance on a continued basis.

Note 2: For affected Airbus A318, A319, A320 and A321 aeroplanes registered in Europe, complying with the approved AMP, as specified in paragraph (3) or (4) of this AD, as applicable, is required by Commission Regulation (EU) [1321/2014](#), Part M.A.301, paragraph 3.

Ref. Publications:

Airbus A318/A319/A320/A321 ALS Part 3 Revision 05, dated 06 April 2017.

The use of later approved variations or revisions of this document is acceptable for compliance with the requirements of this AD.

Remarks:

1. This Proposed AD will be closed for consultation on 12 July 2017.
2. Enquiries regarding this PAD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
3. For any question concerning the technical content of the requirements in this PAD, please contact: AIRBUS – Airworthiness Office – EIAS; Fax +33 5 61 93 44 51;
E-mail: account.airworth-eas@airbus.com.

