



Notification of a Proposal to issue an Airworthiness Directive

PAD No.: 17-077R1

Issued: 01 August 2017

Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

Design Approval Holder's Name:

AIRBUS

Type/Model designation(s):

A318, A319, A320 and A321 aeroplanes

Effective Date: [TBD - standard: 14 days after AD issue date]

TCDS Number(s): EASA.A.064

Foreign AD: Not applicable

Supersedure: This AD supersedes EASA AD 2016-0093 dated 13 May 2016.

ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitations Section – Part 4 – System Equipment Maintenance Requirements – Implementation

Manufacturer(s):

Airbus (formerly Airbus Industrie)

Applicability:

Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A320-251N, A320-271N, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, A321-232, A321-251N, A321-253N and A321-271N aeroplanes, all manufacturer serial numbers.

Reason:

The System Equipment Maintenance Requirements (SEMR) for Airbus A320 family aeroplanes, which are approved by EASA, are currently defined and published in the Airbus A318/A319/A320/A321 Airworthiness Limitations Section (ALS) Part 4 document. These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.



Previously, EASA issued AD 2016-0093 to require accomplishment of all maintenance tasks as described in ALS Part 4 at Revision 03. ALS Part 4 Revision 04 was not mandated because no significant changes were introduced with this Revision. The new ALS Part 4 Revision 05 (hereafter referred to as 'the ALS' in this AD) includes new and/or more restrictive requirements and extends the applicability to model A320-251N, A320-271N, A321-251N, A321-253N and A321-271N aeroplanes.

For the reason described above, this AD retains the requirements of EASA AD 2016-0093, which is superseded, and requires accomplishment of all tasks as described in the ALS.

This PAD is revised to include new aeroplane models in the Applicability and to simplify 'Credit' paragraph (4).

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Maintenance Tasks and Replacement of Life Limited Parts:

- (1) From the effective date of this AD, accomplish the following actions, as specified in the ALS, as applicable to aeroplane model and depending on aeroplane configuration:
 - (1.1) Replace each component before exceeding the applicable life limit, and
 - (1.2) Within the thresholds and intervals (see Note 1 of this AD), accomplish all applicable maintenance tasks.

Note 1: For the purpose of this AD, the limitations, thresholds and intervals as defined in the 'Compliance Time' pages of the ALS include specific compliance times for certain tasks.

Corrective Action(s):

- (2) In case of finding discrepancies during accomplishment of any task as required by paragraph (1) of this AD, before next flight, accomplish the applicable corrective action(s) in accordance with the applicable Airbus maintenance documentation. If a detected discrepancy cannot be corrected by using existing Airbus instructions, before next flight, contact Airbus for approved instructions and accomplish those instructions accordingly.

Aircraft Maintenance Programme (AMP) Revision:

- (3) Within 12 months after the effective date of this AD, revise the approved AMP, on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane, by incorporating the maintenance limitations, tasks, and associated thresholds and intervals described in the ALS, as applicable to aeroplane model and depending on aeroplane configuration.

Credit:

- (4) For an AMP that, on the effective date of this AD, is already updated to incorporate the maintenance tasks and life limitations as specified in a previous ALS Part 4 Revision, that action ensures (see Note 3 of this AD) the continued accomplishment of those tasks and limitations.



Consequently, for an aeroplane to which that AMP applies, it is acceptable to accomplish the new and more restrictive tasks and limitations (see Note 2 of this AD), as applicable to aeroplane model and depending on aeroplane configuration, as defined in, and within the compliance times (see Note 1 of this AD) as specified in, the ALS to comply with paragraph (1) of this AD.

For that AMP, it is acceptable to incorporate the new and more restrictive tasks and limitations (see Note 2 of this AD), as applicable to aeroplane model and depending on aeroplane configuration, as defined in the ALS, into the AMP to comply with paragraph (3) of this AD.

Note 2: For the purpose of this AD, 'the new and more restrictive tasks and limitations' include all tasks and limitations that have been included in the applicable ALS Part 4 since the previous Revision that is currently incorporated in the AMP.

Recording AD compliance:

- (5) When the AMP of an aeroplane has been revised as required by paragraph (3) or (4) of this AD, as applicable, that action ensures (see Note 3 of this AD) continued accomplishment of the tasks and limitations as required by paragraphs (1) and (2) of this AD for that aeroplane. Consequently, after revising the AMP, as required by paragraph (3) or (4) of this AD, as applicable, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

Note 3: For affected Airbus A318, A319, A320 and A321 aeroplanes registered in Europe, complying with the approved AMP as specified in paragraph (3) or (4) of this AD, as applicable, is required by Commission Regulation (EU) [1321/2014](#), Part M.A.301, paragraph 3.

Ref. Publications:

Airbus A318/A319/A320/A321 ALS Part 4 Revision 05, dated 06 April 2017.

The use of later approved variations or revisions of this document is acceptable for compliance with the requirements of this AD.

Remarks:

1. This Proposed AD will be closed for consultation on 15 August 2017.
2. Enquiries regarding this PAD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
3. For any question concerning the technical content of the requirements in this PAD, please contact: AIRBUS – Airworthiness Office – EIAS; Fax +33 5 61 93 44 51; E-mail: account.airworth-eas@airbus.com.

