

COMMENT RESPONSE DOCUMENT

EASA PAD No. 19-043

[Published on 21 March 2019 and officially closed for comments on 04 April 2019]

Commenter 1: ENAC –Giovanni Risalvato & Remo Di Febio – 04/04/2019

Comment # 1

The undersigned are two Airworthiness Inspectors at ENAC North-West Regional Office, based in MXP.

As far as we know, on Falcon F50 / F50EX, also Pacific Scientific squibs p/n 13083-5 can be installed (on the firex of the baggage compartment).

We believe that the matter exposed above is strictly related to the content of the PAD and if confirmed to be applicable to Falcons F50/F50EX probably a further revision of the AD could be imagined.

EASA response:

Comment acknowledged. After coordination with Dassault, it is confirmed that the cartridge P/N 13083-5 is not be considered as an 'Affected part' for the final AD. Indeed, for the cartridge P/N 13083-5, Dassault MPD of the related Dassault AMM for affected aeroplanes mentions a correct value for the "combined service/ storage life".

No changes have been made to the Final AD in response to this comment.