

COMMENT RESPONSE DOCUMENT

EASA PAD No. 20-118

[Published on 10 August 2020 and officially closed for comments on 07 September 2020]

Commenter 1: Lufthansa Technik – Rene Schinkel – 02/09/2020

Comment # 1

Required Action (1): Please define what “next shopvisit” means in reference to RR Generic EMP. Does it also apply to Hospital Shopvisits and other Shopvisits where the engine is not disassembled?

EASA response:

Comment noted. The shop visit as referred to in the AD is ‘any’ shop visit, therefore including “Hospital” shop visits. In Rolls-Royce documentation, the definition of a shop visit only excludes a “serviceability check”, i.e. where the engine is just put across a test bed (not disassembled in any way).

No changes have been made to the Final AD in response to this comment.

