



Airworthiness Directive

AD No.: 2022-0105

Issued: 10 June 2022

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301 or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303 or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS S.A.S.

Type/Model designation(s):

A380 aeroplanes

Effective Date: 24 June 2022

TCDS Number(s): EASA.A.110

Foreign AD: Not applicable

Supersedure: This AD supersedes EASA AD 2019-0217 dated 02 September 2019 and EASA AD 2020-0198 dated 15 September 2020.

ATA 05 – Time Limits / Maintenance Checks – Safe Life Airworthiness Limitations Items – ALS Part 1 – Amendment

Manufacturer(s):

Airbus

Applicability:

Airbus A380-841, A380-842 and A380-861 aeroplanes, all manufacturer serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

The ALS: Airbus A380 Airworthiness Limitations Section (ALS) Part 1 Revision 12.

The AMP: The approved Aircraft Maintenance Programme (AMP) on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane. For A380 aeroplanes operated under EU regulation, compliance with the approved AMP is required by Commission Regulation (EU) [1321/2014](#), Part M.A.301, paragraph (c).



New and/or more restrictive limitations: This includes all limitations that are new and all limitations for which a threshold was reduced, which were introduced into the ALS (as defined in this AD) since the previous ALS Revision that is currently incorporated in the AMP.

Reason:

The airworthiness limitations for the Airbus A380, which are approved by EASA, are currently defined and published in the Airbus A380 ALS document(s). These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.

EASA previously issued AD 2019-0217 to require the actions described in Airbus A380 ALS Part 1 Revision 11, and AD 2020-0198 to require the actions described in Airbus A380 ALS Part 1 Variation 11.1.

Since those ADs were issued, Airbus published the ALS, as defined in this AD, which contains new and/or more restrictive limitations.

For the reason described above, this AD retains the requirements of EASA AD 2019-0217 and AD 2020-0198, which are superseded, and requires accomplishment of the actions specified in the ALS.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Replacement of Life Limited Parts:

- (1) From the effective date of this AD, replace each component before exceeding the applicable life limit, as specified in the ALS, as applicable to aeroplane model and depending on aeroplane configuration.

AMP Revision:

- (2) Within 12 months after the effective date of this AD, revise the approved AMP by incorporating the limitations described in the ALS, as applicable to aeroplane model and depending on aeroplane configuration.

Credit:

- (3) If, before the effective date of this AD, the AMP has been revised to incorporate the limitations as specified in a previous ALS revision, that action ensures the continued accomplishment of those limitations.

Consequently, for an aeroplane to which that AMP applies, it is acceptable to accomplish the new and more restrictive limitations, as applicable to aeroplane model and depending on aeroplane configuration, as defined in, and within the compliance times as specified in, the ALS, to comply with paragraph (1) of this AD.

For that AMP, it is acceptable to incorporate the new and more restrictive limitations, as applicable to aeroplane model and depending on aeroplane configuration, as defined in the ALS, into the AMP to comply with paragraph (2) of this AD.



Recording AD Compliance:

- (4) When the AMP of an aeroplane has been revised as required by paragraph (2) or (3) of this AD, that action ensures continued accomplishment of the limitations as required by paragraph (1) of this AD for that aeroplane. Consequently, after revising the AMP, as required by paragraph (2) or (3) of this AD, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

Ref. Publications:

Airbus A380 ALS Part 1 Revision 12 dated 01 March 2022.

The use of later approved revisions or variations of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 12 May 2022 as PAD 22-055 for consultation until 09 June 2022. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS S.A.S. – 1IANA (Airworthiness Office), Telephone: +33 562 110 253, Fax: +33 562 110 307, E-mail: account.airworth-A380@airbus.com.

