

COMMENT RESPONSE DOCUMENT

EASA PAD No. 23-056

[Published on 11 May 2023 and officially closed for comments on 08 June 2023]

Commenter 1: ELIABRUZZO SRL – Nicola Capuzzi – 12/05/2023

Comment # 1

For the serviceable assembly (page 1), I suggest to use the P/N 350A27-5627-00 of the support plate assembly (that contains the microswitches) because the P/N 350A08-8756-0071 reported on the PAD refers to the retrofit kit (plate assembly plus all the screws, bolts, washers, etc required to apply the ASB).

EASA response:

Comment agreed. The definition of the serviceable assembly has been amended.

