



Notification of a Proposal to issue an Airworthiness Directive

PAD No.: 24-075

Issued: 01 July 2024

Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

Design Approval Holder's Name:

AIRBUS S.A.S.

Type/Model designation(s):

A321 aeroplanes

Effective Date: [TBD - standard: 14 days after AD issue date]

TCDS Number(s): EASA.A.064

Foreign AD: Not applicable

Supersedure: None

ATA – Aircraft Flight Manual / Complementary Performance Data File – Amendment

Manufacturer(s):

Airbus, formerly Airbus Industrie

Applicability:

Airbus A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, A321-232, A321-251N, A321-251NX, A321-252N, A321-252NX, A321-253N, A321-253NX, A321-271N, A321-271NX, A321-272N and A321-272NX aeroplanes, all manufacturer serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

CPDF update: Complementary Performance Data File (CPDF) CD32FM04 dated 24 June 2023.

AFM: Aircraft Flight Manual (AFM) A318/A319/A320/A321 dated 05 July 2023.

Reason:

An erroneous value of main landing gear (MLG) tyre width has been identified in the A321 Aircraft Data Files used for the aircraft performance computation. The MLG tyre width is used for the



calculation of performance on contaminated runways (water, slush, dry snow or wet snow runway states), especially for the drag modelling.

This situation, if not corrected, could result in erroneous (non-conservative) calculation of certain data, including, but not limited to, take-off distance and accelerate stop distance, possibly leading to runway excursions.

To address this potential unsafe condition, Airbus issued the CPDF, including corrected aeroplane performance data base.

For the reason described above, this AD requires to update the performance database.

Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the action(s) required by this AD have been already accomplished:

AFM Update:

- (1) Within 3 months after the effective date of this AD, implement the CPDF update in the AFM, inform all flight crews, and, thereafter, operate the aeroplane accordingly.
- (2) Amending the AFM of an aeroplane by incorporating a later AFM revision, which includes the same content as in the CPDF update, is an acceptable method to comply with the requirements of paragraph (1) of this AD for that aeroplane.

Ref. Publications:

Airbus AFM A318/A319/A320/A321 dated 05 July 2023.

Complementary Performance Data File (CPDF) CD32FM04 dated 14 June 2023.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. This Proposed AD will be closed for consultation on 29 July 2024.
2. Enquiries regarding this PAD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
3. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this PAD, and which may occur, or have occurred on a product, part or appliance not affected by this PAD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this PAD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.



4. For any question concerning the technical content of the requirements in this PAD , please contact: AIRBUS – Airworthiness Office – 1IASA; E-mail: account.airworth-eas@airbus.com .

