

## Notification of a Proposal to issue an Airworthiness Directive

**PAD No.:** 24-086

**Issued:** 12 July 2024

Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

**Design Approval Holder's Name:**

AIRBUS S.A.S.

**Type/Model designation(s):**

A380 aeroplanes

**Effective Date:** [TBD - standard: 14 days after AD issue date]

**TCDS Number(s):** EASA.A.110

**Foreign AD:** Not applicable

**Supersedure:** None

### ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitations Section Part 1, Safe Life Airworthiness Limitations Items – Amendment

**Manufacturer(s):**

Airbus

**Applicability:**

Airbus A380-841, A380-842 and A380-861 aeroplanes, all manufacturer serial numbers.

**Definitions:**

For the purpose of this AD, the following definitions apply:

**The Variation:** Airbus A380 Airworthiness Limitations Section (ALS) Part 1, Safe Life Airworthiness Limitations Items (Revision 12), Variation 12.1.

**The AMP:** The Aircraft Maintenance Programme (AMP) contains the tasks on the basis of which the scheduled maintenance is conducted to ensure the continuing airworthiness of each operated aircraft. For aircraft operated under EU regulation the operator or the owner ensures compliance with the AMP as stipulated in Commission Regulation (EU) [1321/2014](#).

**New and/or more restrictive limitations:** This includes all limitations that are new and all limitations for which a threshold or interval was reduced, which were introduced through the Variation, as defined in this AD, since the previous ALS revision that is currently incorporated in the AMP.

**Reason:**

The airworthiness limitations for the Airbus A380, which are approved by EASA, are currently defined and published in the Airbus A380 ALS documents. These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.

EASA previously issued AD 2022-0105, requiring the actions described in Airbus A380 ALS Part 1, Safe Life Airworthiness Limitations Items, Revision 12.

Since that AD was issued, Airbus published the Variation, which contain(s) new and/or more restrictive limitations. These limitations are expected to be incorporated into the Airbus A380 ALS Part 1 at the next revision.

For the reason described above, this AD requires accomplishment of the actions and limitations specified in the Variation. EASA AD 2022-0105 is not superseded by this AD.

**Required Action(s) and Compliance Time(s):**

Required as indicated by this AD, unless the action(s) required by this AD have been already accomplished:

**Replacement of Life Limited Parts:**

- (1) From the effective date of this AD, replace each component before exceeding the applicable life limit, as specified in the Variation, as applicable to aeroplane model and depending on aeroplane configuration.

Where this AD requires a task which is already required per EASA AD 2022-0105, the instructions of the Variation invalidate the instructions of Airbus A380 ALS Part 1 Revision 12.

**AMP Revision:**

- (2) Within 12 months after the effective date of this AD, revise the approved AMP by incorporating the limitations, and associated thresholds and intervals described in the Variation, as applicable to aeroplane model and depending on aeroplane configuration.

**Recording AD Compliance:**

- (3) When the AMP of an aircraft has been revised as required by paragraph (2) of this AD, as applicable, that action ensures continued accomplishment of the limitations as required by paragraph (1) of this AD for that aircraft. Consequently, after revising the AMP, as required by paragraph (2) of this AD, as applicable, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.



**Ref. Publications:**

Airbus A380 ALS Part 1, Safe Life Airworthiness Limitations Items (Revision 12), Variation 12.1 dated 11 April 2024.

The use of later approved revisions of the above-mentioned document, or of an ALS revision which includes the technical content of the Variation, is acceptable for compliance with the requirements of this AD.

**Remarks:**

1. This Proposed AD will be closed for consultation on 09 August 2024.
2. Enquiries regarding this PAD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
3. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this PAD, and which may occur, or have occurred on a product, part or appliance not affected by this PAD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this PAD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
4. For any question concerning the technical content of the requirements in this PAD, please contact: AIRBUS S.A.S. – IIANA (Airworthiness Office), Telephone: +33 562 110 253, or Fax: +33 562 110 307, E-mail: [account.airworth-A380@airbus.com](mailto:account.airworth-A380@airbus.com).

