

COMMENT RESPONSE DOCUMENT

EASA PAD No. 24-095

[Published on 25 July 2024 and officially closed for comments on 22 August 2024]

Commenter 1: FedEx Express – Brian Moore – 21/08/2024

Comment # 1

1. The proposed Airworthiness Directive (AD) will be effective for 71 A300-600 model airplanes operated by FedEx Express.
2. FedEx Express has determined that the expanded effectivity required per SB A300-57-6118 R02 adds 6 A300-600 model airplanes operated by FedEx Express and will fit within our planned scheduled maintenance checks. Therefore, there will be no impact to available lift.
3. The number of man-hours and elapsed time to accomplish SB A300-57-6118 R02 inspections and modification will not impact the overall span-time of our planned, scheduled maintenance check unless a crack is found requiring repair.
4. The proposed AD inspections and modification do not require any special inspection techniques, training or tooling.

EASA response:

Comments noted. No change has been made to the Final AD in response to this comment

