

# Notification of a Proposal to issue an Airworthiness Directive

PAD No.: 24-116

# Issued: 15 October 2024

Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

**Design Approval Holder's Name:** 

Type/Model designation(s): A330 aeroplanes

Effective Date:	[TBD - standard: 14 days after AD issue date]
TCDS Number(s):	EASA.A.004
Foreign AD:	Not applicable
Supersedure:	This AD supersedes EASA AD 2021-0246R1 dated 12 October 2022.

# ATA 05 – Time Limits / Maintenance Checks – Safe Life Airworthiness Limitations Items – ALS Part 1 – Amendment

# Manufacturer(s):

AIRBUS S.A.S.

Airbus, formerly Airbus Industrie

## **Applicability:**

Airbus A330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, A330-343, A330-841 and A330-941 aeroplanes, all manufacturer serial numbers.

## **Definitions:**

For the purpose of this AD, the following definitions apply:

The ALS: Airbus A330 Airworthiness Limitations Section (ALS) Part 1 Revision 13.

**The AMP**: The Aircraft Maintenance Programme (AMP) contains the tasks on the basis of which the scheduled maintenance is conducted to ensure the continuing airworthiness of each operated aeroplane. For aeroplanes operated under EU regulation the operator or the owner ensures compliance with the AMP as stipulated in Commission Regulation (EU) <u>1321/2014</u>.



**New and/or more restrictive tasks**: This includes all tasks that are new and all tasks for which a threshold or interval was reduced, which were introduced into the ALS (as defined in this AD) since the previous ALS revision that is currently incorporated in the AMP.

## Reason:

The airworthiness limitations instructions for the Airbus A330 aeroplanes, which are approved by EASA, are currently defined and published in the A330 ALS document(s). These instructions have been identified as mandatory for continued airworthiness. The airworthiness limitations applicable to the Safe Life Airworthiness Limitations Items are specified in ALS Part 1.

Failure to accomplish these instructions could result in an unsafe condition.

Previously, EASA issued AD 2021-0246, later revised, to require accomplishment of all maintenance tasks as described in ALS Part 1 at Revision 11.

Since that AD was issued, Airbus published the ALS, as defined in this AD, to introduce new and/or more restrictive tasks.

For the reason described above, this AD retains the requirements of EASA AD 2021-0246R1, which is superseded, and requires accomplishment of the actions specified in the ALS.

# **Required Action(s) and Compliance Time(s):**

Required as indicated by this AD, unless the action(s) required by this AD have been already accomplished:

# Maintenance Tasks:

(1) From the effective date of this AD, replace each component before exceeding the applicable life limit, as specified in the ALS, as applicable to aeroplane model and depending on aeroplane configuration.

## AMP Revision:

(2) Within 12 months after the effective date of this AD, revise the AMP by incorporating the limitations described in the ALS, as applicable to aeroplane model and depending on aeroplane configuration.

## Credit:

(3) If, before the effective date of this AD, the AMP has been revised to incorporate the life limitations as specified in a previous revision of Airbus A340 ALS Part 1, that action ensures the continued accomplishment of those limitations.

Consequently, for an aeroplane to which that AMP applies, it is acceptable to accomplish the new and/or more restrictive tasks, as defined in this AD, as applicable to aeroplane model and depending on aeroplane configuration, within the compliance times as specified in the ALS to comply with paragraph (1) of this AD.



For that AMP, it is acceptable to incorporate the new and/or more restrictive tasks, as defined in this AD, as applicable to aeroplane model and depending on aeroplane configuration, into the AMP to comply with paragraph (2) of this AD.

# **Recording AD Compliance**:

(4) When the AMP of an aeroplane has been revised as required by paragraph (2) or (3) of this AD, as applicable, that action ensures continued accomplishment of the tasks as required by paragraph (1) of this AD for that aeroplane. Consequently, after revising the AMP, as required by paragraph (2) or (3) of this AD, as applicable, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

## **Ref. Publications:**

Airbus A330 ALS Part 1 Revision 13 dated 01 October 2024.

The use of later approved variations or revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

#### **Remarks:**

- 1. This Proposed AD will be closed for consultation on 12 November 2024.
- 2. Enquiries regarding this PAD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: <u>ADs@easa.europa.eu</u>.
- 3. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this PAD, and which may occur, or have occurred on a product, part or appliance not affected by this PAD, can be reported to the <u>EU aviation safety reporting system</u>. This may include reporting on the same or similar components, other than those covered by the design to which this PAD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
- 4. For any question concerning the technical content of the requirements in this PAD, please contact: AIRBUS 1IAL (Airworthiness Office), E-mail: <u>airworthiness.A330-A340@airbus.com</u>.

