



EASA Safety Information Notice

No.: 2008-17

Issued: 28 February 2008

Subject: Engine rotating group parts and components that have been improperly maintained and returned to service

Ref. Publication: FAA Unapproved Parts Notification (UPN) No. 2008- S20071128005.

Introduction: The Federal Aviation Administration (FAA) has published the referenced UPN (attached as pages 2 through 5 of this notice) as a result of an investigation that revealed that engine rotating group parts and component have been improperly maintained and returned to service, contrary to regulations.

Applicability: Any aircraft and/or engines, as applicable, which have engine rotating group parts and components installed, as identified in the attached FAA UPN. The FAA has been unable to determine the affected aircraft and engines (type designs).

Recommendation: This Safety Information Notice is for information only.

Contact: For further information contact the Airworthiness Directives, Safety Management and Research Section, Certification Directorate, EASA.
E-mail: ADs@easa.europa.eu .