



## EASA Safety Information Notice

No.: 2008-23

Issued: 12 March 2008

**Subject:** Cabin Controllers and Outflow Valves that have been improperly maintained and returned to service

**Ref. Publication:** FAA Unapproved Parts Notification (UPN) No. 2008-S200708310320.

**Introduction:** The Federal Aviation Administration (FAA) has published the referenced UPN (attached as pages 2 through 4 of this notice) as a result of an investigation that revealed that certain cabin controllers and outflow valves have been improperly maintained, overhauled and returned to service, contrary to regulations.

**Applicability:** Any aircraft which have cabin controllers and/or outflow valves installed, as identified in the attached FAA UPN. The FAA has not determined the aircraft type designs on which these components are (intended to be) installed.

**Recommendation:** This Safety Information Notice is for information only.

**Contact:** For further information contact the Airworthiness Directives, Safety Management and Research Section, Certification Directorate, EASA.  
E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu) .