



## EASA Safety Information Bulletin

**SIB No.:** 2012-12  
**Issued:** 28 June 2012

**Subject:** Notification of Unapproved Parts due to theft

**Ref. Publication:** None.

**Applicability:** Various aircraft.

**Description:** Ente Nazionale Aviazione Civile (ENAC) Italy has informed that in a period of time between January 2012 and May 2012, several parts and equipment were stolen from an aircraft which was on long term parking since 2009. The certificate of airworthiness of the affected aircraft had been suspended by ENAC in April 2009.

The affected parts and equipment are the following:

COMPONENT	MANUFACTURER	PART NUMBER	SERIAL NUMBER
FMS, Control Display Unit	Honeywell	7007549-906	96042023
Oxygen Mask	B/E Aerospace Oxygen	174260-14	07666
DC-Bus Power Control Unit	Auxilec / Thales (Thompson)	106-000-4	1328
Anti Skid Control Unit	Dunlop Aviation	AE20874-1	0260
			0205
Flap Control Unit	Liebherr	1050A0000-04	00277
Electronic Control Unit	Orbit Advanced Technologies	23180-000-02	IL0332
DC Generator Control Unit	Auxilec / Thales (Thompson)	118-000-31	1062
			1078
Dimmer	Diehl	3296-40	2023
PA Amplifier	Avtech	5382-1	263
Data Acquisition Unit	Honeywell	7013348-936	98111477
			99051824

This is information only. Recommendations are not mandatory.

Navigation unit	Honeywell	7510100-631	99093911
			00024180
Integrated Avionic Computer	Honeywell	7017300-11125	99081776
		7017300-14125	99081744
Attitude and Heading Reference Unit	Honeywell	HG2010AC02	99061102
			99071162
AC Generator Control Unit	Auxilec / Thales (Thompson)	2438-31	1076
			1037
Proximity Sensor Electronic Unit	Aerospace Avionics Inc	714400-2	0999053
TCAS computer	ACSS	7517900-10003	01064663
Data Loader System	Honeywell	7016600-902	99031679
Cockpit Voice Recorder	L3 Communications	2100-1020-00	00753
Flight Data Recorder	L3 Communications	2100-4043-00	00615
Emergency Power Supply	B.F. Goodrich	PS835C	10844

**Recommendation:** The parts and equipment contained in the above list have to be considered unapproved and not eligible for installation on an aircraft.

Owners, operators and maintenance organizations are encouraged to inspect their aircraft and inventories for the referenced part numbers and corresponding serial numbers. If any of these parts and equipment is found on board the aircraft or stored in the inventory, it is recommended to remove and quarantine it, to prevent its installation. It is also recommended to inform accordingly the competent authority and ENAC - Airworthiness and Operations Regulation Divisions. E-mail: [regolazione.navigabilita@enac.gov.it](mailto:regolazione.navigabilita@enac.gov.it).

**Contact:** For further information contact the Safety Information Section, Executive Directorate, EASA. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).

This is information only. Recommendations are not mandatory.