EASA SIB No.: 2015-02R2



Safety Information Bulletin Operations

SIB No.: 2015-02R2

Issued: 16 October 2015

Subject: Pakistan Airspace

Ref. Publications:

- 1) AIC France Circular A 23/15 issued by DGAC-France (see Appendix 1).
- 2) NOTAM AFP56646 issued by United Kingdom Civil Aviation Authority (UK CAA) (see Appendix 2).

Applicability:

National Aviation Authorities and aircraft operators.

Description:

The Agency draws the aviation community's attention to the above referenced information.

This SIB revision 1 dated 25 February 2015 was issued to modify EASA recommendation.

This SIB revision 2 is issued to introduce a reference to UK CAA NOTAM AFP56646 and to update the reference to AIC France Circular issued by DGAC France (The content of AIC France Circular A 23/15 has remained unchanged for Pakistan in comparison to previous version).

Recommendation(s):

National Aviation Authorities should ensure that operators under their oversight are aware of the above referenced publications.

Abbreviations:

Safety Information Bulletin SIB:

Contact(s):

For further information contact the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.



EASA SIB No.: 2015-02R2

Appendix 1: AIC France Circular A 23/15 issued by DGAC-France



TECHNICAL SERVICE

a : +33 (0)5 57 92 57 57 Fax : +33 (0)5 57 92 57 77

: sia-direction@aviation-civile.gouv.fr Site SIA: http://www.sia.aviation-civile.gouv.fr

AIC FRANCE A 23/15

Publication date: OCT 15

SUBJECT: OVERFLIGHT OF CONFLICT ZONES

This AIC cancels and supersedes AIC A 05/15

1 Introduction

1.1 This circular lists the areas outside the national territory subject to overflight restrictions or penetration prohibitions issued by the French authorities to French air carriers.

2 General considerations

- 2.1 Exceptional waivers may be granted upon motivated request to the competent authority.
- 2.2 These restrictions or prohibitions apply without prejudice to emergency measures that the pilot in command may take in case of absolute necessity.

3 List of concerned areas

3.1 Ukraine

From 17/07/2014 and until further notice, French carriers are requested not to authorize their aircraft to penetrate into the airspace of Ukraine (UKBV FIR (KYIV), UKDV (DNIPROPETROVS'K), UKFV (SIMFEROPOL), UKOV (ODESA), UKLV (L'VIV)), except for flights to and from Kiev airport UKBB (KYIV/BORYSPIL).

3.2 Ira

From 31/07/20 14 and until further notice, French carriers are requested not to authorize their aircraft to penetrate into the airspace of Iraq (ORBB FIR (BAGHDAD)).

3.3 Libva

From 31/07/2014 and until further notice, French carriers are requested not to authorize their aircraft to penetrate into the airspace of Libya (HLLL FIR (TRIPOLI)).

3.4 Syria

From 31/07/2014 and until further notice, French carriers are requested not to authorize their aircraft to penetrate into the airspace of Syria (OSDI FIR (DAMASCUS)).

3.5 Afghanistan

From 17/01/2015 and until further notice, French carriers are requested to ensure that their aircraft maintain at all times a flight level equal to or above FL240 in the airspace of Afghanistan (OAKX FIR (KABUL)).

3.6 Pakistan

From 17/01/2015 and until further notice, French carriers are requested to ensure that their aircraft maintain at all times a flight level equal to or above FL240 in the airspace of Pakistan (OPLR FIR (LAHORE) and OPKR FIR (KARACHI)).

3.7 Yemer

From 27/03/2015 and until further notice, French carriers are requested not to authorize their aircraft to penetrate into the airspace of Yemen (OYSC FIR (SANA'A)).

3.8 Sudan and South Sudan

From 27/03/2015 and until further notice, French carriers are requested to ensure that their aircraft maintain at all times a flight level equal to or above FL240 in the airspace of Sudan and South Sudan (HSSS FIR (KHARTUM)).

3.9 Iran

From 15/10/2015 and until further notice, French carriers are requested to ensure that their aircraft maintain at all times a flight level equal to or above FL240 in the northwest part of the airspace of Iran (OIIX FIR (TEHERAN)) located between the FIR boundary and a straight line linking the following coordinates: 372100N 0535500E and 295110N 0484500E.

3.10 Somalia

From 15/10/2015 and until further notice, French carriers are requested to ensure that their aircraft maintain at all times a flight level equal to or above FL240 in the airspace of Somalia (HCSM FIR (MOGADISHU)).



EASA SIB No.: 2015-02R2

Appendix 2: NOTAM AFP56646 issued by United Kingdom Civil Aviation Authority (UK CAA)

Group: M CAA HOUSE / User: M LONDON 1A/UIS UTC Time: 2015.10.08-14:13:10

AFP5664 081411

GG EGPFLOGX EGPFZXAO EGPKYWYO EGQAYWYO EGQLZGZX EGQMYWYO EGQMZXAF EGQSYWYF EGQSYWYO EGQSZXCO EGTCZTZX EGTEZTZX EGTTZDZM EGTTZRZN EGUBYWYO EGUBZGZX EGUCYWYO EGULYWYO EGULZXBO EGUOZXAF EGUUYVYX 081410 EUECYIYN

(V0055/15 NOTAMN

- Q) EGXX/QROXX/IV/NBO/W /000/999/5218N01451W999
- A) EGGX EGPX EGTT B) 1510081400 C) 1601072359
- E) HAZARDOUS SITUATION IN PAKISTAN. POTENTIAL RISK TO AVIATION OVERFLYING KARACHI AND LAHORE FIRS AT LESS THAN 25,000FT ABOVE GROUND LEVEL (AGL) FROM DEDICATED ANTI-AVIATION WEAPONRY. OPERATORS ARE ADVISED TO TAKE THIS INFORMATION INTO ACCOUNT IN THEIR OWN RISK ASSESSMENTS AND ROUTEING DECISIONS. CONTACT UK DEPARTMENT FOR TRANSPORT (+44) (0)20 7944 3260 OR (+44) (0)207 944 5999 OUT OF HOURS. ON EXPIRY OF THIS NOTAM DETAILS WILL BE INCLUDED IN THE UK AIP ENR 1.4 AIRSPACE WARNINGS BY THE DEPARTMENT OF TRANSPORT.
- F) SFC
- G) UNL
- F) SFC G) UNL)

