

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE
RELEASED BY THE SECRETARIAT GENERAL
FOR CIVIL AVIATION

The inspections or modifications described below are mandatory. Failure to comply with Airworthiness Directives entails suspension of the Certificate of Airworthiness (see decree regarding airworthiness requirements for civil aircraft).

AEROSPATIALE HELICOPTERS -
SA 341 G GAZELLE

FUEL SYSTEM - LE BOZEC 433 B 25.1 AND 433 B 25.12 FILTERS

In order to ensure satisfactory positioning of the filter element in the above-referenced filters and so avoid inefficient operation due to faulty assembly, the following mandatory instructions are issued for application immediately upon receipt of parts and by December 15 th, 1973 at the latest.

- a/ - Replace guide, P/N LB.81.692.1, by a long locating guide, P/N LB.81.692.2.
- b/ - If the free length of spring, P/N LB.82.456.1 is greater than 34 mm, replace the spring with P/N LB.82.456 spring.

After embodiment, add suffix "A" to the part number.

REFERENCE : AEROSPATIALE SERVICE-BULLETIN SA 341 GAZELLE N° 28.02.

Translation of "Consigne de Navigabilité
Réf. 73-127-7 "

In case of any difficulty, reference
should be made to the French original text.

Date : 27.11.73

Material : AEROSPATIALE HELICOPTER -
SA 341 G GAZELLE

Reference : 73.127.7