

**BUREAU VERITAS**

**AIRWORTHINESS DIRECTIVE  
RELEASED BY THE SECRETARIAT GENERAL  
FOR CIVIL AVIATION**

The inspections or modifications described below are mandatory. Failure to comply with Airworthiness Directives entails suspension of the Certificate of Airworthiness (see decree regarding airworthiness requirements for civil aircraft)

AEROSPATIALE HELICOPTERS - SA 341 G

GAZELLE

FUSELAGE - Addition of a deflector to the fuel tank air vent.

.....

In order to preclude any risk of creating a negative pressure in the fuel tank, detrimental to the reading accuracy of the fuel contents indicator and to the strength of attachment on the flexible fuel tank, the addition of a deflector secured to the body structure, behind the fuel tank vent opening, has been rendered mandatory in the following conditions :

On the occasion of the next scheduled inspection of airframe or after the next 100 running hours at the latest.

.....

REFERENCE : AEROSPATIALE SERVICE-BULLETIN GAZELLE No 53.02

Translation of "Consigne de Navigabilité

Réf. 74-12-9 "

In case of any difficulty, reference  
should be made to the French original text.

Date : 15.1.74

Material : AEROSPATIALE HELICOPTER  
SA 341 G GAZELLE

Reference : 74-12-9