

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE
RELEASED BY THE SECRETARIAT GENERAL
FOR CIVIL AVIATION

The inspections or modifications described below are mandatory. Failure to comply with Airworthiness Directives entails suspension of the Certificate of Airworthiness (see decree regarding airworthiness requirements for civil aircraft).

AEROSPATIALE HELICOPTERS - ALOUETTE II AND ALOUETTE ASTAZOU (ALL VERSIONS)

INSPECTION OF DRAG DAMPERS

(effective for drag dampers P/N 3130.13.50.000 all dash numbers and 3130.13.60.000 all dash numbers)

Following the findings made on aircraft during operation a check for correct operation of the drag dampers was made mandatory in accordance with the manufacturer's directives (ALOUETTE SERVICE-BULLETIN No 05-54) in the following cases :

- on the occasion of every removal/installation of a damper
 - when the A/C vibration level is found abnormally high
-

Reference : AEROSPATIALE SERVICE-BULLETIN ALOUETTE No 05-54

DATE OF EFFECTIVITY : 17th JUNE 1975

Translation of "Consigne de Navigabilité
Réf. 75-99-32"

In case of any difficulty, reference
should be made to the French original text.

Date : 10.6.75

Material : AEROSPATIALE HELICOPTERS
ALOUETTE II AND ALOUETTE

Reference : 75-99-32