

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by Direction Générale de l'Aviation Civile

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. :86-17-14(B)
In case of any difficulty, reference should
be made to the French original issue.

AEROSPATIALE HELICOPTERS DAUPHIN SA 365 N

Fuel Filter

The present Airworthiness Directive applies to AEROSPATIALE SA 365 N DAUPHIN helicopters equipped with LE BOZEC fuel filters P/N 433G 20-2 or P/N 433G 20-2 Amendment A (LH and RH sides).

In order to check the fuel flow at the by-pass valve outlet on LH and RH fuel filters, the checking instructions given in paragraph 1.C of AEROSPATIALE SA 365 N Service Bulletin Nr. 01-12 are hereby rendered mandatory and shall be complied with within the next 50 hours time in service after the effective date of this Airworthiness Directive.

NOTE 1 : The checking instructions prescribed above are to be complied with prior to any flight after installation of a LE BOZEC fuel filter the part number of which (433G 20-2 or 433G 20-2 Amendment A) is not suffixed with letter "X".

NOTE 2 : After satisfactory compliance with checking instructions prescribed above, letter "X" shall be engraved on the filter body, following the part number marking.

NOTE 3 : The present Airworthiness Directive is not applicable to filters P/N 433G 20-2 X, P/N 433G 20-2 Amendment AX and P/N 433G 20-2 Amendment B and subsequent.

Ref. : AEROSPATIALE SA 365 N S.B. Nr. 01-12

EFFECTIVE DATE : FEBRUARY 12, 1986.

FEBRUARY 5, 1986

**AEROSPATIALE HELICOPTERS
DAUPHIN SA 365 N**

Ref. : 86-17-14(B)