

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by Direction Générale de l'Aviation Civile

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 87-114-032(B)
In case of any difficulty, reference should
be made to the French original issue.

AEROSPATIALE AS 332 Helicopters

Reduction of the service life of the tail rotor blades

This Airworthiness Directive concerns all versions of AEROSPATIALE AS 332 helicopters equipped with tail rotor blades P/N :

332 A 12-0010.01 and .05

332 A 12-0030.09 and .11

332 A 12-0035.03 and .04

From the date this Airworthiness Directive comes into effect, the service life limit of the above referenced tail rotor blades is reduced from 9 200 hours to 4 400 hours.

Cf. : AEROSPATIALE AS 332 Service Bulletin N° 01-19

EFFECTIVE DATE : ON RECEPTION

Date : 19/08/1987

AEROSPATIALE AS 332 Helicopters

Ref. : 87-114-032(B)