

BUREAU VERITAS

## AIRWORTHINESS DIRECTIVE

released by Direction Générale de l'Aviation Civile

*Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of "Consigne de Navigabilité"  
Réf. : 87-173-009(B)  
In case of any difficulty, reference should  
be made to the French original issue.

### ATR 42 A/C

Protection for auto pilot roll actuator

This directive applies to ATR 42.200 and ATR 42.300 A/C, all serial numbers.

In order to prevent the auto pilot roll actuator against the running water effects following measures are rendered mandatory from the effective date of the present Airworthiness Directive :

- 1/ - The modification in Bulletin Service ATR 42.22.0006 (MOD 1475) is made mandatory before January 1st, 1988.
- 2/ - The modification in Bulletin Service ATR 42.22.0005 (MOD 1457) is made mandatory before March 13th, 1988.

NOTA : Modification 1475, has yet been rendered mandatory by telex issued from DGAC on December 4th, 1987.

EFFECTIVE DATE : DECEMBER 19, 1987

Dec. 9, 1987

ATR 42 A/C

Réf. : 87-173-009(B)